

The Sportsman CTR.

Trigger was adjusted improperly outside factory. Trigger
retraction spring force was insufficient to properly
return trigger and connector underneath rear - safety cam

2 types of sealant on trigger adjusting screws, one of
which appeared to be an epoxy. Could not remove
sealant properly to effect adjustment.

* The gun will FS R because of improper retraction spring
force