

RECEIVING AND ESTIMATING REPORT

COMMENTS

INITIAL FPS	CUSTOMER ORDER NO					
DATE RECEIVED 02/28/91	DATE OPENED 03/06/91	DATE CODE DR 9-68	SERIAL NUMBER 370141	MODEL AND GRADE 700 30-06	ORDER R 21-06453	
ACCESSORIES L/BARREL			L/REAR SIGHT			

FROM:

SHAW, JEFF
2389 DUNE DR
C/O SHAW BROS ROOFING CO
AVALON NJ 08202

SHIP TO:

SHAW, JEFF
2389 DUNE DR
C/O SHAW BROS ROOFING CO
AVALON NJ 08202

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM DATE	ESTIMATED 3-14	VIA UPS
----------------	--------------------	--------------------------------	------------	-----------	-------------------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:

☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

Handwritten: Gun is faulty, has defective, fired once when
carefully checked, sometimes firing 2 or 3 rounds after
trigger pulled.

MAIN FAULT

Handwritten: Cannot diagnose complaint, however, trigger assembly and firing
pin assembly are contaminated with excessive oil and dirt. This
in combination with cold temperature could explain the delayed firing.

PARTS

Handwritten: Clean firing pin and trigger assembly,
if possible. Or, we can install a
new trigger assembly at a normal
cost, as a gesture of good-will, if it
will better restore confidence in
the rifle.

REPAIRMAN BWT	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 7/90

PS05843