

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 91-23953

INITIAL

CUSTOMER ORDER NO.

JIM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

11/19/91

11/22/91

00 7-77

A6488854

700 270

BDL

ACCESSORIES

W/STUDS

L/SIGHTS

FROM:

SHIP TO:

SHOWKER, SKIP
157 GREENVILLE AVE
P O BOX 2573
STAUNTON
USA

VA 24401

SHOWKER, SKIP
157 GREENVILLE AVE
P O BOX 2573
STAUNTON
USAVA
24401

CUST NO: 053411 C.O.D

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

FROM DATE

ESTIMATED

VIA

11/22/91

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Above malfunction could not be duplicated, after many attempts. Trigger and safety assembly operate properly. However, trigger assembly has been improperly adjusted (outside factory) (screw missing from screw). 1) Trigger pull is below our min spec - measured at 2.7 pounds 2) Over travel is excessive

Sear lift - .010"

PARTS

Please set up file
Attached copy to
Sergeant

COMMENTS

Offer to properly re-adjust present trigger assembly for, we can install a new trigger assembly at a nominal cost, as a gesture of good-will, if it will better restore confidence in the rifle.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV 8/91

PS05853