

Repair Order Number



Repair Order Number RE00052781	Description/Serial Number 6501077	Repairman - Chuck Dekanek
Account # - R-	Model 700 Center Fire Caliber: 243 ADL	Date Received - 10/11/2002
		Estimate Date -
		Current Date - 10/17/2002
Customer PAT THOMPSON 2313 MERCURY CORPUS CHRISTI. TX 78409 US		Return To PAT THOMPSON 2313 MERCURY CORPUS CHRISTI. TX 78409 US
Phone (H) (361)-289-5574	Fax (361)-289-1320	
Phone (W)	Email advancedpumper@aol.co	

Reported		Problems		Found	
M238	CLEAN & INSPECT	M123	FORWARD TO PRODUCT SERVICE		
M992	UNINTENTIONAL FIRINGS				

Material #		MaterialDesc	Repair			Warranty
			Quantity Needed	Quantity From Inv	Quantity From Kit	(Y/N)
Part						
F26345	700	TRIG ASSB RH	1	1	0	Y
Part Total:			1	1	0	
Service						
4000104	ARMS SERV	SHIPPING & HANDLING	0	0	0	Y
4000116	GR-LABOR		20	20	0	N
4000119	GR-TEST		1	1	0	Y
4000294	GR-CHECK	TPA	1	1	0	Y
Service Total:			22	22	0	

ProblemNotes Action dirty-covered with dust.Replace trigger assembly \$20.00 per DJS.

Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date


10 LBS 1 OF 1

REMINGTON ARMS CO INC
800 243-9700
14 HOEFLER AVE
ILION NY 13357

SHIP

TO:

PAT THOMPSON
2313 MERCURY
CORPUS CHRISTI TX 78409




TX 784 9-01



UPS GROUND

TRACKING #: 1Z 114 813 03 1196 6362



BILLING: P/P

INV#: RE00052781

ASC 05.00 J69X/J64X 16.0A 01/2002