

Repair Order Number



Repair Order Number RE00050895	Description/Serial Number 6355976	Repairman - Robert Frink Date Received - 8/22/2002
Account # - R-	Model 700 Center Fire Caliber: 270 BDL	Estimate Date - 8/20/2002 Current Date - 8/28/2002
Customer TOM TOWNLEY 5412 WESTRIDGE RD ANAHEIM. CA 92807 US	Return To TOM TOWNLEY 5412 WESTRIDGE RD ANAHEIM. CA 92807 US	
Phone (H) (714)-998-2810 Phone (W)	Fax Email	

Reported		Problems	Found
M238	CLEAN & INSPECT	M123	FORWARD TO PRODUCT SERVICE F
M992	UNINTENTIONAL FIRINGS	M238	CLEAN & INSPECT
		M239	REPLACE TRIGGER ASSEMBLY

Material #		MaterialDesc	Repair	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part							
F26345		700 TRIG ASSB RH		1	1	0	Y
Part Total:				1	1	0	
Service							
4000104		ARMS SERV SHIPPING & HANDLING		0	0	0	Y
4000116		GR-LABOR		20	20	0	N
4000118		GR-CLEAN		1	1	0	Y
4000119		GR-TEST		1	1	0	Y
Service Total:				22	22	0	

ProblemNotes Action dirty. All 3 adjustment screws altered. Clean action and replace trigger assembly. D.S.

Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date


10 LBS 1 OF 1

REXINGTON ARMS CO INC
800 243-9700
14 HOEFLER AVE
ILION NY 13357

SHIP

TO:

TOM TOWNLEY
5412 WESTRIDGE RD
ANAHEIM CA 92807




CA 927 9-01



UPS GROUND

TRACKING #: 1Z 114 813 03 1193 4422



BILLING: P/P

INV#: RE00050895

ASC 05.00 J69K/J64K 16.0A 01/2002