

Repair Order Number



Repair Order Number RE00075181	Description/Serial Number 376845	Repairman - Robert Frink Date Received - 1/21/2004
Account # - R-	Model 700 Center Fire Caliber: 3006 BDL	Estimate Date - 1/15/2004 Current Date - 1/27/2004
Customer JOHN TEAGUE 2232 DEFOORS FERRY RD NW ATLANTA, GA 30318 US	Return To JOHN TEAGUE 2232 DEFOORS FERRY RD NW ATLANTA, GA 30318 US	
Phone (H) (404)-350-7884 Phone (W) (404)-218-0862 XCEL	Fax Email JLTTEAGUE@MSN.CC	

Reported		Problems Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE FOR
M240	BOLT LOCK SAFETY MODIFICATION	M238	CLEAN & INSPECT (SAFETY PROGR.
M992	FIRES WHEN SAFETY IS MOVED TO FIRE POSITI	M239	REPLACE TRIGGER ASSEMBLY

Material #		MaterialDesc		Repair		Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part									
F26345		700 TRIG ASSB RH				1	1	0	Y
Part Total:						1	1	0	
Service									
4000104		ARMS SERV SHIPPING & HANDLING				0	0	0	Y
4000116		GR-LABOR				20	20	0	N
4000118		GR-CLEAN				1	1	0	Y
4000119		GR-TEST				1	1	0	Y
Service Total:						22	22	0	

ProblemNotes	Upon receipt we could not duplicate the reported fires when safety is moved to fire. Trigger adjustment and stop screws have been backed out. Some rust found on trigger housing. Replace trigger assembly for \$20.00. D.S.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date