



United States Department of the Interior

U.S. GEOLOGICAL SURVEY

Robert Oscarson Mail Stop 919
345 Middlefield Road
Menlo Park, CA 94025
650 329-5117
roacarson@usgs.gov

Remington Arms
Attn: Arm Services
14 Hoefler Avenue
Ilion, New York 13357

Model: 700

Firearm serial # A 6615736

Recondition this firearm to factory specification. Please call me with an estimated cost if any major components (barrel or receiver) need to be replaced.

Additional comments:

Bolt retainer malfunctions, bolt pulls out w/o depressing release.

+ Firing pin falls when safety is released with trigger pulled. This may be normal.

Bolt release hangs-up/sticks

+ Safety can be applied with bolt open.

11/14/03 Trig Assm Components covered with a brown sticky substance - Part working shipped. →
Replace Trig Assm 20.00 and estimate including workmanship

*Out of stock
XQ
12/18*