Remington Arms Co., Inc.
Product Service
Legal Case #:2232

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete

142440 3/12/2008 3/13/2008 3/13/2008

**Customer Information** 

Type Business First Name Last Name Street City State Zip Age Contact

Reporter Gander Mtn Gander Mtn 151 Market Square Blvd Tyler TX 75703 W 903-839-8205

Incident Information

Claims Codes Repair Medical Medical Status

ΡI

PD Cause: 4006 Altered Adjustments or

G fired on safe Cause.4000 Components Unknown

release Concern: 1007 Fired on Safe Release

C

3/14/08-correspondence from repair-moved safety to off and gun fired. Bolt is loose.lw

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. DOM

Remington CF/BA 7/243 WIN 24760 S7637352 ET 10/11/1999 8:26:48 AM

Date Purchased Where Purchased Accessories Original Owner

MCBRIDES GUNS INC SCOPE BASE U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/7/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement APV APV

Repair at discount

Repair/Replacement Repair/Replacement
Cost Date

Cost E 3/14/08-quote sent to repair at discount.lw

Examination[Remington/CF/BA]

Part	Part Sub-Part		Comment		
	Examiner		<b>B.TRAVIS</b>		
Examination	Exam Date		3/13/2008		
	Product Type		RF		
	Action Type		A		
	Assigned To		F.SUPRY		

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=2232&Type=Case

3/14/2008

Cause	4006	Altered Adjustments or Components			
	Description		20" 243 WIN		
Barrel	Date Code		ET		
	Bore Plugged	False			
	Bulged	False			
	Fired	False			
	Fired while Obstructed		_		
	Muzzle/Crown Condition	Slightly Worn; Functioning	]		
Bolt	Firing Pin	Slightly Worn; Functioning			
	Shroud	Slightly Worn; Functioning			
	Face	Slightly Worn; Functioning	]		
	Handle	Slightly Worn; Functioning	1		
	Stop	Slightly Worn; Functioning	<u> </u>		
Extractor	Condition	Slightly Worn; Functioning	<u> </u>		
	Cut Condition	Slightly Worn; Functioning	]		
	Ext/Eject Test	False	]		
**************************************	Block Condition	Select			
Locking	Lug Condition	Slightly Worn; Functioning			
	Notch Condition	Select			
Overall	Exterior Condition	Slightly Worn; Functioning			
	Stock Condition	Slightly Worn; Functioning	]		
	Fore End Condition	Select	]		
Receiver	Condition	Slightly Worn; Functioning	1		
	Bulged	False			
Safety	Description		STANDARD M/7 SAFETY		
	Function	Like new; Functioning			
	Sub-Assembly	Non-ISS			
Sear	Lift	Select	.013		
	Notch	Like new; Functioning			
	Tasta	Test Fired	False		
Feeding Test	Tests	False			
T	Condition	Slightly Worn; Functioning	]		
	Pull	Select	2.5#		
Trigger	Altered	True	SET SCREWS ALTERED		
	Sub-Assembly	Other Remington	]		
Non-Remington Com	ponents Description		SCOPE BASE		



# Service Request Service Order # 1434

## SHIPPED TO VENDOR/STORE:

Remington Arms Co, Inc.

14 Hoefler Ave

Llion, NY 13357 Attn: Repairs

Date Shipped: 02/23/2008

Phone: (800) 243-9700

## **RETURN SHIP TO:**

Gander Mountain. FFL# 5-75-423-01-9b-03021

Attn: Gun Parts Dept. 151 Market Square Blvd.

Tyler, TX 75703

## FIREARM INFORMATION:

Manufacturer: Remington Arms Co Inc.

Type:

Rifle

Serial Number: S7637352

Cased?:

Model:

seven

Cal/Ga.: .243cal

# **DESCRIPTION OF ITEM RETURNED:**

Rem model seven 243 cal serial # S7637352

## **REASON FOR RETURN:**

Customer was in a deer stand an moved safety to off an gun fired. Bolt is extremely loose in action and will lockup in the rear when you try to chamber another shell to the chamber.

## ATTENTION VENDOR

Please contact me with any questions or concerns.

Billy Nash (903) 839-8205

## **BILLING INFORMATION:**

Please include the service order number on all invoices and correspondence:

SHIP TO ABOVE ADDRESS

Forward all invoices to:

180 East 5th Street

**Suite 1300** 

St. Paul, MN 55101

S7637352

Model:

could not dupliente concerno set screus arrenes. Replace TRA, check over, clear at 1/2 NORMAL Charges.

tapeth (miptility).		White have					
	erial: \$7637352 Model 7 43 WIN Produced: 10/11		Repairman .	Chuck Dekanek alHold 3/13/2008 9		- 17 of	
eniÿ Repair	e setti ist		учась   Аррго	/airi0i0/3/13/2006	45 17 AM		
Gustomer		n Return To GANDER M	OLINITAINI	€ Receive	d From		
Name: GANDER MOUNTAIN ddiess 1: ATTN CINDY KILBRIDE	<u> </u>	and the second s	SQUARE BLVD	<u> </u>		f. 18	
ddiess 2: 180 E 5TH ST SUITE 1300  City: SAINT PAUL	P0 Box	TYLEA		PO Box		34.7	
State MN Zip Code 55101	Country: US		de (75703	Country US			Carlotte Andrews
		FILT T					opologica series
Contact / Condition Prot	lems	Estimate	History / Status	Shipping	/Billing		46-8-04-4
o lo lo lo	50 4 m 1 m 1 m 1 m 1 m 1 m 1 m 1 m 1 m 1 m	and the second second		Current S	atus		
Date	Desc1 Repair Added	Desc2	☐ Shipping Hold	Approva 3/13/2008 9			
3/12/2008 1:19:5 Update valentds 3/12/2008 1:20:1 Update valentds	Repair information changes Repair information changes		Estimate Sent	dekane	keg		
3/12/2008 1:22:4 Expedite valentds	From: Check In	To:	☐ Parts Received	Repair Lo	C4 45 25 25 1 1 1 1 1		
3/13/2008 7:58.5 Expedite travisbw 3/13/2008 9:43.1 Estimate dekanekco	From: Product Services Estimate Update	To: Repair Bench Status: ApprovalHold	Γ Passed Inspect Γ Return As Rec	ion ILN			
	THE W		I Heturn As Heco ☐ Has been Appr	Section 1	ication 7		
	1.5		Γ Internal Repair	Transfer N			
		Internal Control		1			
Repair <u>S</u> earch				<u>R</u> efresh	<u>C</u> lose		
	no de la companya de						
	Andread and the second	South the first transfer of transfer of transfer of transfer of th		ecano programa	oder to the		
a position of the same of the		Section of the sectio		* 556 Beer 1			
	antical and to complete a light	App.		Lucia			and make on the
1		Sold Language			A Charge on the Control of the Contr	The state of the American	
《美国主》(《 <del>经验经》</del> 为"大概")。(15日)	[27] [2] [4] [4] [4] [4] [4] [4] [4] [4] [4] [4	The Art of the same of the	i vayna ar i	*****************************		部はは解析が、	

LAURA,

We could not dopticate concern. We

found the set screw positions altered. We

will install a new TA and clean the Adim

at to normal charges.

Feed.