Remington Arms Co., Inc. Product Service Legal Case #:3738

Case Information

Date Opened Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete RE#

174268 9/2/2009 9/3/2009 9/3/2009

Customer Information

Type Business First Name Last Name City State Zip Age Contact Street H 772-332-1691

555 E Forest Tr Vero Beach FL 32962 Incident William Haggerty E Haggerty555@comcast.net

Incident Information

Claims Repair Est. Medical Treatment Medical Status Codes

ΡĮ

PD fires when safety is

Cause:4013 Broken or Missing Parts

Concern: 1028 Fired With Safe ON

Unknown

engaged

9/8/09 Per letter with rifle, trigger and safety do not work correctly - sometimes trigger does not work and sometimes when safety is engaged the trigger fires.cm

Firearm Information

Mfg. Remington

Type CF/BA

Model/Ga. 600/308 WIN

SKU 20000 Serial Bbl. DOM

Date

Accessories

Original Owner

6646541 KX 5/1/1973

Purchased

Where Purchased STEM DIST MAPLE HTS OHIO

SCOPE BASE, HARD CASE, SLING

U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/600/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Cash Settlement Date APV

Reim.

Cash Date **APV**

replace TPA under recall at n/c

> Repair/Replacement Repair/Replacement

Cost

Date

48.09

9/8/2009

9/8/09 Sear engagement screw missing from trig assm. Replace TPA under recall at n/c.cm

Examination[Remington/CF/BA]

Sub-Part	Code	Comment
Examiner		B.TRAVIS
Exam Date		9/3/2009
Product Type		RF
	Examiner Exam Date	Examiner Exam Date

*	Action Type		A
	Assigned To		F.SUPRY
Cause	4013	Broken or Missing Parts	HAS NOT BEEN UPDATED
	Description		18.5" 308 WIN
	Date Code		KX
Barrel	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed	i	-
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning]
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	Ĩ
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/600 BOLT LOCK SAFETY
	Function	Like new; Functioning]
Sear	Lift	Select	N/A
	Notch	Slightly Worn; Functioning	
	Toota	Test Fired	False
Feeding Test	Tests	False]
Trigger	Condition	Slightly Worn; Not Functioning	
	Pull	Select	N/A
	Altered	True	SEAR ENGAGEMENT SCREW MISSING
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		SCOPE BASE,HARD CASE,SLING

epair Inquiny			eports Table Maintenance S	/ Scell) Frankerian	e Help	
epair Number RE00174268	Serial: 664654 Caliber: 308 V	1 Model 600 M0HAWK Center F /IN Produced: 05/16/1973		Bruce Travis d 9/3/2009 5:30:	22 AM	9
dress Information	1		na a stira digirira majar daga dama kanagina mara a dama mahari mana			er and market and the
Customer:	the state of the s	to a contract the contract of		Received	From	
Name: WILLIAM HAGGERT	Y	WILLIA	MHAGGERTY			A. The Company of th
Idress 1: 555 E FOREST TRL	tomericonarum minimum minimi di manisalia m	555 E FC	REST TRL		4.00	
Idress 2:	P0 Box			Box		经营税单分子的基础
City: VERO BEACH		VERO BI				化化物体的分类 化物
State: FL Zip Code: 32962	Cou	ntry: US State: FL	Zip Code: 32962	Country: US		· 医中国中部中的 1000
		FFL:		r		
			<u>,</u>	<u> </u>		and the first of the second
Contact / Condition	Problems	E stimate	History / Status	Shipping / I	illing	化化二甲甲基甲基甲基
		4		Current Stat	us	
Date Code	User ID	Desc1	Shipping Hold	PartsHol	da a a a a a a a a a a a a a a a a a a	有一直的人 在1964年
9/2/2009 8:20:37 New	VALENTDS	Repair Added	InterFace Hold	9/3/2009 5:30		and the second second
9/2/2009 8:26:24 Expedite	VALENTDS	From: Check In		Travisby	The second secon	
9/2/2009 8:33:35 Update	VALENTDS	Repair information change	Estimate Sent	PartsRac	1 1 300 4000	
9/3/2009 5:26:25 Maint	Travisbw	Repair Maintenance	Parts Received	Repair Loca	tion	
9/3/2009 5:30:22 Estimate	Travisbw	Estimate Update	Passed Inspection	ILN		
9/3/2009 6:00:28 PartsHold	System	Immediate SAP Allocation	Return As Receive		1 1 2 2 2 2 2 2 2	美国电影 医动物
9/3/2009 6:09:11 Expedite	Travisbw	From: Repair Bench		HILL	The state of the s	and the last of th
			Has been Approved	Transfer Nu	mber	A de la Prima de Constanti
<u> 11</u>			I Internal Repair	13 25 25		
Repair <u>S</u> earch			Dat	resh (,	
Wehait Zearcit		요즘 사용은 중시간 회사가 있는 것	v nijerio de la Contraction de	<u> </u>	lose	
				1.30	100000	
						e de la companya de
496			the profession of the first	archie es d'aplice	and the second second	with the second second
		in the state of the state of		o Balanda da Alba		化基苯基化物 电电影
					and the second	ude anceroups to record at all out
Constitution of the second section	19 10 19 19 19 19		4484666			
	100					
				or become		

12 15 21.09 48.09

General Repair Form

Back to Repair Services

NOTE: Please complete and print this form, and then include it with your firearm

Model Number: Mohawk 600	Serial Number: 6646541						
Name: William Haggerty	Date of Purchase: March 1986						
Address (no PO Boxes): 555 East Forest Tr							
City: Vero Beach	State: FL	Zip: 32962					
Phone (Daytime): 772-332-1691	Fax:						
E-mail Address: Haggerty555@comcast.net							
trigger and safety do not work correctly – sometimes trigger does safety is engaged trigger fires.	es not work and sometimes when	·					
373 characters left		· .					
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.							
① WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.							

Record the serial number of your firearm before sending it.
Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)
Remove all accessories from your firearm to prevent loss or damage.
Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss

during shipment, so you may elect to purchase insurance from your carrier.



Visit Our Other Websites

Sear engagement screw Missing. Crom Trig. ASSM. Replace TPA UNDER NEW MAT A/C

230145