Remington Arms Co., Inc.
Product Service
Legal Case #:3828

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 176562 9/30/2009 10/1/2009 10/1/2009

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Incident Larry Henderson 1324 Old Fort Rd Monicks Corner SC 29461 H 843-899-5114
C 843-697-1247

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

PD fired on bolt

Cause:4038 Could Not Duplicate Concern

Unknown

S closing

Concern: 1008 Fired on Bolt Closing

C

10/5/09 Owner alleges that after several years of use the rifle started firing when he closed the bolt. He took it to a local gunsmith twice to tighten the trigger, first time it reoccured, hasn't happened since the 2nd tightening.cm

Firearm Information

Mfg.

Type

Model/Ga.

SKU

Serial Bbl. DOM

Remington Date

CF/BA Where 700/270 WIN

Original

6686768 RX 11/1/1973

Purchased

Purchased

Accessories

Original

U

TWO PIECE SCOPE BASE, LEATHER STOCK

BOOT

CONCERN:FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim. Settlement Date APV Cash Date APV

replace TPA under BLSM program

Repair/Replacement Repair/Replacement

Cost Date 60.39 10/5/2009

10/5/09 Could not duplicate concern. Replace TPA, check over, clean, under BLSM program for \$20 + S&H.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		10/1/2009
	Product Type		RF

Action Type	_	[A
Assigned To		F.SUPRY
4038	Could Not Duplicate Concern	
Description		22" 270 WIN
Date Code		RX
Bore Plugged	False	
Bulged	False	
Fired	False	
Fired while Obstructed		_
Muzzle/Crown	Slightly Worn;	
Condition		_
Firing Pin	Functioning	
Shroud	Functioning	
Face	Slightly Worn; Functioning	
Handle	Worn; Functioning	
Stop	Slightly Worn; Functioning	
Condition	Slightly Worn; Functioning	
Cut Condition	Slightly Worn; Functioning	
Ext/Eject Test	False	
Block Condition	Select	
Lug Condition	Slightly Worn; Functioning	
Notch Condition	Select	
Exterior Condition	Slightly Worn; Functioning	
Stock Condition	Slightly Worn; Functioning	
Fore End Condition	Select	
Condition	Slightly Worn; Functioning	
Bulged	False	
Description		STANDARD M/700 BOLT LOCK SAFETY
Function	Like new; Functioning	
Lift	Select	.007
Notch	Slightly Worn; Functioning	
Tests	Test Fired	False
10303	False	
Condition	Slightly Worn; Functioning	DIRTY/RUSTY
<u> </u>		
	Description Date Code Bore Plugged Bulged Fired Fired while Obstructed Muzzle/Crown Condition Firing Pin Shroud Face Handle Stop Condition Cut Condition Ext/Eject Test Block Condition Lug Condition Exterior Condition Stock Condition Fore End Condition Condition Bulged Description Function Lift Notch Tests	Description Date Code Bore Plugged False Bulged Fired Fired False Fired while Obstructed Muzzle/Crown Condition Firing Pin Slightly Worn; Functioning Shroud Face Fised Handle Worn; Functioning Stop Slightly Worn; Functioning Condition Slightly Worn; Functioning Stightly Worn; Functioning Face Slightly Worn; Functioning Condition Slightly Worn; Functioning Stightly Worn; Functioning Cut Condition Functioning Slightly Worn; Functioning Cut Condition Functioning Slightly Worn; Functioning Slightly Worn; Functioning Slightly Worn; Functioning Slightly Worn; Functioning Functioning Functioning Slightly Worn; Functioning Notch Condition Slightly Worn; Functioning Functioning Fore End Condition Slightly Worn; Functioning Fore End Condition Functioning Functioning Bulged False Description Function Functioning False False False Slightly Worn; Functioning

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=3828&Type=Case

	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE,LEATHER STOCK BOOT

Arms Services Repair & Estimate System	
File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System	n Maintenance Help.
5 Repair Inquiry	
Repair Number: RE00176562 Serial: 6686769 Model 700 Center Fire Caliber: Repairman: Bruce Travis	
Verify Repair Status: ApprovalHold 10/1/2009 7:18:09 AM	and the displacement of the property of the con-
Address Information Customer: General From Return To. Centering From Received From Re	
Name: LARRY HENDERSON LARRY HENDERSON	
Address 1: 31324 OLD FORT ROAD 1324 OLD FORT ROAD 1324 OLD FORT ROAD PO Box PD Box	A CONTRACTOR OF THE SECTION
City: MONCKS CORNER MONCKS CORNER State: SC Zip Code: [29461 Country: [US State: SC Zip Code: [29461 Country: [US	the second of th
State of the state	
Contact / Condition Problems Estimate History / Status Shipping / Billing	Carrier and Carrie
Current Status	
9/30/2009 12:47 New valentds Repair Added InterFace Hold 10/1/2009 7:18:09 AM	
10/1/2009 6:41:5 Maint Travisbw Repair Maintenance Estimate Sent Appropries According to Appropriate Sent Ap	A CONTRACTOR OF THE RESIDENCE
10/1/2009 7:18:C Estimate Travisbw Estimate Update Parts Received Repair Location 10/1/2009 7:20:C Approval-Hold System Immediate SAP Allocation Passed Inspection ILN	A CONTRACTOR OF THE PARTY OF
10/1/2003 8:08:4 Expecte Pencell From: Hepail Bench Return As Received Cuttent Location	
Transfer Number	
Repair Search Refresh Cose	美国生活的 医多种性多种 医神经神经
	· · · · · · · · · · · · · · · · · · ·
A. L.	
在是他的是我们的是是不是一个的。 第二章	
· 是自身的现在分词 医自身性 医自身性 医神经炎	· 每 ~ 4 ~ 2 ~ 4 + 1 ~ 2 ~ 2 ~ 2 ~ 2 ~ 2 ~ 2 ~ 3 ~ 3 ~ 3 ~ 3
	The state of the s
多数多数数字数字数字数字数字数数字数数数	
· · · · · · · · · · · · · · · · · · ·	
the state of	AND A CONTRACTOR OF THE
	Control of the first of the fir
Suppl 10/1/2009 923AM (DPS NUN DE SESSEN)	Z@∏%(60)∃)9 ven'
SERVI GIBORA HIPOSOICE IN CONTRESENCES IN PARTICIONALE IN CONTRESENCES IN CONT	

Bott Lock Modification program

12 35 15 35-39 -37 60.39

DECEIVE OCT 02 2009 BY:----- 3828

Remington Repair 2009

Sept 24, .

22" 67

After several years of use this rifle started fireing when I closed the bolt-I didn't touch the trigger. I took it to a gun smith and he tightened the trigger. A short time later it happened again. Fortunately I was sighting the rifle in and it was pointed down range. The gun smith tightened the trigger again and put loc tight on it and it hasn't happened again but the trigger pull is way too heavy. I like a trigger pull 3-31/2 pounds. Please put this rifle thru your SMP program. E-Mail me at lhenderson@carolinaone.com and I will send you a check or a credit card no. which ever you prefer.

Sincerely,

Larry G. Henderson

Hans ph. 843-849-5114 Cell - 843-697-1247

6686768 Model: 700

RE00176562

could not duplicate concern. Ruplace TPA, check over, elean under BOLT LOCIL PROGRAM CON \$ 20.00 + Stot

H