

Remington Arms Co., Inc.
Product Service
Legal Case #:4000

Case Information

| RE# | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|--------|-------------|-----------------|-------------|---------------|---------|-----|----------|
| 180704 | 11/18/2009 | 11/19/2009 | 11/19/2009 | | | | |

Customer Information

| Type | Business | First Name | Last Name | Street | City | State | Zip | Age | Contact |
|----------|-----------|------------|-----------|-------------------|-------|-------|-------|-----|--|
| Reporter | Somarriba | * | Somarriba | 12161 SW 131 Ave. | Miami | FL | 33186 | | W 305-252-6677 F 305-252-8008 E info@somarriba.com |

Incident Information

| Claims | Codes | Repair Est. | Medical Treatment | Medical Status |
|--------|-----------------------------------|------------------------------------|-------------------|----------------|
| PI | | | | |
| PD | | | | |
| S | Cause:4006 | Altered Adjustments or Components | Unknown | |
| C | Headspace & fired on Safe release | Concern:1007 Fired on Safe Release | | |

Dealer reported in a letter - Sold gun to customer. Customer returned the rifle & stated - Shells get stuck after firing. Rifle fired once when the Safety was taken off. Customer's hunting trip was ruined. Dealer requested the rifle be replaced. dmf

Firearm Information

| Mfg. | Type | Model/Ga. | SKU | Serial | Bbl. | DOM |
|----------------|------------------|----------------------|----------------|----------|------|-----------------------|
| Remington | CF/BA | 700/300 WIN MA | 27049 | G6460598 | BZ | 1/13/2005 10:45:17 PM |
| Date Purchased | Where Purchased | Accessories | Original Owner | | | |
| | SPORTS SOUTH INC | TWO PIECE SCOPE BASE | U | | | |

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

| Settlement | Release of Claims | Release Date | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|---------------------------|-------------------------|-------------------------|---------------|-----------------|----------------|---------------|
| Repair at 1/2 normal cost | | | | | | |
| | Repair/Replacement Cost | Repair/Replacement Date | | | | |

11/20/09: Per Fred S. - Headspace is ok. Could not duplicate concern. Trigger set screws altered. Replace trigger at 1/2 normal cost. Check over & repair as needed. dmf

Examination[Remington/CF/BA]

| Part | Sub-Part | Code | Comment |
|------|-----------|------|------------|
| | Examiner | | B.TRAVIS |
| | Exam Date | | 11/19/2009 |

| | | | |
|--------------------------|------------------------|-----------------------------------|--------------------|
| Examination | Product Type | RF | |
| | Action Type | A | |
| | Assigned To | F.SUPRY | |
| Cause | 4006 | Altered Adjustments or Components | |
| Barrel | Description | 26" 300 WIN MAG | |
| | Date Code | BZ | |
| | Bore Plugged | False | |
| | Bulged | False | |
| | Fired | False | |
| | Fired while Obstructed | | |
| | Muzzle/Crown Condition | Slightly Worn; Functioning | |
| Bolt | Firing Pin | Slightly Worn; Functioning | |
| | Shroud | Slightly Worn; Functioning | |
| | Face | Slightly Worn; Functioning | |
| | Handle | Slightly Worn; Functioning | |
| | Stop | Slightly Worn; Functioning | |
| Extractor | Condition | Slightly Worn; Functioning | |
| | Cut Condition | Slightly Worn; Functioning | |
| | Ext/Eject Test | False | |
| Locking | Block Condition | ---Select--- | |
| | Lug Condition | Slightly Worn; Functioning | |
| | Notch Condition | ---Select--- | |
| Overall | Exterior Condition | Slightly Worn; Functioning | |
| | Stock Condition | Slightly Worn; Functioning | |
| | Fore End Condition | ---Select--- | |
| Receiver | Condition | Slightly Worn; Functioning | |
| | Bulged | False | |
| Safety | Description | STANDARD M/700 SAFETY | |
| | Function | Like new; Functioning | |
| | Sub-Assembly | Non-ISS | |
| Sear | Lift | ---Select--- | .015 |
| | Notch | Like new; Functioning | |
| | Tests | Test Fired | False |
| Feeding Test | | False | |
| Trigger | Condition | Like new; Functioning | |
| | Pull | ---Select--- | 3# |
| | Altered | True | SET SCREWS ALTERED |
| | Sub-Assembly | M/700 Non-Bolt Lock | |
| Non-Remington Components | Description | TWO PIECE SCOPE BASE | |



Somarriba, Inc.

Rifle Makers, Gunsmiths, & Hunting Outfitters
12161 SW 131 Avenue - Miami, FL 33186

Tel. 305-252-6677 Fax. 305-252-8008 Email info@somarriba.com

4000

PURCHASE ORDER

| DATE | P.O. NO. |
|------------|----------|
| 11/10/2009 | 6993 |

DU

| | |
|---|----------------|
| Vendor | |
| REMINGTON ARMS SERVICE DIVISION 14 HOEFLER AVENUE ILION, NY 13357 USA | |
| TEL | 1-800-243-9700 |
| FAX | 336-548-7801 |

| |
|--|
| Ship To |
| SOMARRIBA, INC. 12161 SW 131 AVE MIAMI, FLORIDA 33186 305 252 6677 fax 305 252 8008 |

BZ 1/05
3#
26"
015

| DESCRIPTION | SNO | QTY | RATE | AMOUNT |
|---|----------|-----|------|--------|
| Remington Model 700 S#G6460598 caliber 300 Win Mag This is a brand new rifle we sold. Our customer returned the rifle with the following complaints: 1. <input type="checkbox"/> Shells get stuck after firing. The bolt closes on a NO GO gauge. This indicated an abnormal chamber. 2. <input type="checkbox"/> Customer also complaints that rifle fired once when safety was taken off. Furthermore; the above conditions ruined our customer's hunting trip. This rifle is considered unsafe by our customer and we are very much concerned about safety ourselves. We would you to please replace this rifle inasmuch as our customer is very disappointed. Your prompt attention to this matter is greatly appreciated. | G6460598 | 1 | | 0.00 |
| <p>Headspace is OKAY. could not duplicate concern. TITG. Set screws ALTERED replace TPA at 1/2 normal cost. check over + repair as needed. Quote</p> | | | | |
| Total | | | | \$0.00 |

Serial Number:

G6460598

Model: 700



RE00180704

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Maintenance Help

RECEIVED
NOV 20 2009

BY: