Remington Arms Co., Inc. Product Service Legal Case #:5153

Case Information RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Obsolete 211043 11/19/2010 11/22/2010 11/22/2010 Customer Information City Zip Age Last Name Street Contact Type Business First Name State W 602-200-0943 3828 N. 28th Ave. Phoenix 85017 Reporter Magnum Precision Magnum Precisio AZ F 480-858-9001 Incident Information Claims Codes Repair Est. Medical Treatment **Medical Status** ΡI PD Cause: 4038 Could Not Duplicate Concern Unknown S Concern: 1007 Fired on Safe Release C FSR Dealer wrote a note. They stated the owner of the rifle claims that the safety doesn't work correctly & he can get it to fire by pushing the safety Firearm Information Model/Ga. SKU DOM Mfg. Type 700/243 WIN 27355 3/1/2007 12:46:28 AM CF/BA G6650217 LB Remington Original Owner Where Purchased Accessories **Date Purchased** SPORTS SOUTH INC IJ

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim. Date Cash Date
Settlement APV APV

Per Ilion - Quote to repair

CONCERN:FSR

Repair/Replacement Cost Repair/Replacement Date

Per Ilion - Could not duplicate concern. Trigger set screws altered. Can offer to replace TA, clean & test fire @ 1/2 normal charges - quote. df 12/10/10: I called store about quote & spoke to Jeff. He asked me to fax quote & he would send payment. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date •		11/22/2010
Examination	Product Type		RF
ļ	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
	Description		22" 243 WIN
	Date Code		LB
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		•
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5153&Type=Case

12/10/2010

Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
			
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
B	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
Safety	Description		STANDARD M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	.013
	Notch	Like new; Functioning	
	T	Test Fired	False
Feeding Test	Tests False		
	Condition	Slightly Worn; Functioning	
7	Pull	Select	2.5#
Trigger	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	

QUOTATION

Remington Arms Company, Inc. 870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

ESTIMATING REPORT

Parts/Repairs Fax

800-243-9700 336-548-7801

www.remington.com info@remington.com

AVILEPTIGES OUOTED AREJINEX CHANGE FOR REPLACED PARTS

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (4) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 15 DAYS, WE SHALL RETURN THE ITEM(S) AS RECEIVED POSTAGE DUE.

Repair Order RE00211043							
RE00211043		Description/Serial Nur	nber			eceived -	11/19/2010
		G6650217				te Date -	11/22/2010
Account # - R	-				Curren	it Date -	12/10/2010
Customer				Return T	n		
	PRECISION			MAGNU	-	MOISE	
3828 N 28T				3828 N 2			
	1111.2				V		
PHOENIX.	AZ 85017 US			PHOENI	X. AZ 85	5017 US	
Phone (H)	(602)-200-0943		Fax				
Phone (W)			Email				
Please Circle (Τ	- .		
	AMEX DISCOVER Card No	·		Exp. 1	Date		
PO Number _							
	e(Оре	n Acet. <u>R</u>		
Approval: Cus	stomer Signature					Date_	
If You	Desire Any Change Please Use T	he Reverse Side For You	ır Comments	s And Mark T	his Box		
	• •	tice: We process checks elec-					
		. Problen	ns				
Reported .			Found :				
A Company of the Comp			Comment of the Commen				
M123	FORWARD TO PRODU	CT SERVICE	M123	FORV	VARD TO	PRODUC'	Γ SERVICE F
	FOR INSPECTIO	-					
ļ							
L							
		- Technician's C	omments%			200	
		lechnician's C	TO MAN COLUMN TO THE PARTY OF T	A STATE OF THE PARTY OF THE PAR	AND THE PERSON NAMED IN		
ProblemNote	es could not duplicate cond	ern.trigger assm set sc	TO MAN COLUMN TO THE PARTY OF T	A STATE OF THE PARTY OF THE PAR	AND THE PERSON NAMED IN	trigger plate	assm,clean
ProblemNote		ern.trigger assm set sc	TO MAN COLUMN TO THE PARTY OF T	A STATE OF THE PARTY OF THE PAR	AND THE PERSON NAMED IN	trigger plate	e assm,clean
ProblemNote	es could not duplicate cond	ern.trigger assm set sc	TO MAN COLUMN TO THE PARTY OF T	A STATE OF THE PARTY OF THE PAR	AND THE PERSON NAMED IN	trigger plate	e assm,clean
ProblemNote	es could not duplicate cond	ern.trigger assm set sc	TO MAN COLUMN TO THE PARTY OF T	A STATE OF THE PARTY OF THE PAR	AND THE PERSON NAMED IN	trigger plate	e assm,clean
	es could not duplicate conc and test fire at 1/2 norm	cern trigger assm set sc al charges.	rews altered	d.can offer t	o replace		
	es could not duplicate conc and test fire at 1/2 norm	cern trigger assm set sc al charges.	rews altered	d.can offer t	o replace	Quote :	
	es could not duplicate conc and test fire at 1/2 norm	cern trigger assm set sc al charges.	rews altered	d.can offer t NOT Includ Warranty	o replace to replace t	Quote	<u>Extended</u>
<u>Material</u> #	es could not duplicate conc and test fire at 1/2 norm	cern trigger assm set sc al charges.	rews altered	d.can offer t	o replace	Quote :	
<u>* Material #</u> Part	es could not duplicate conc and test fire at 1/2 norm Estimate	cern trigger assm set scal charges. hipping and Handling C	rews altered Charges are Oty	d.can offer t NOT includi Warranty Y/N	o replace i ed in this (<u>Price/</u> <u>Unit</u>	Quote Sunt Discount Percent	Extended Amt
Material # Part F305570B	es could not duplicate conc and test fire at 1/2 norm	cern trigger assm set scal charges. hipping and Handling C	rews altered Charges are Oty	d.can offer t NOT includi Warranty Y/N	o replace to replace t	Quote	<u>Extended</u>
<u>* Material #</u> Part	es could not duplicate conc and test fire at 1/2 norm Estimate	cern trigger assm set scal charges. hipping and Handling C	rews altered Charges are Oty	d.can offer t NOT includi Warranty Y/N	o replace i ed in this (<u>Price/</u> <u>Unit</u>	Quote Sunt Discount Percent	Extended Amt
Material # Part F305570B	es could not duplicate conc and test fire at 1/2 norm Estimate. C.O.D./S Material Description X-MARK PRO 700 TRIG A	cern trigger assm set scal charges. hipping and Handling C	rews altered Charges are Oty	d.can offer t NOT includi Warranty Y/N	o replace i ed in this (<u>Price/</u> <u>Unit</u>	Quote Sunt Discount Percent	Extended Amt
Material # Part F305570B Service	es could not duplicate conc and test fire at 1/2 norm Estimate	cern trigger assm set scal charges. hipping and Handling C	charges are Oty	NOT includ Warranty Y/N N	o replace to the control of the cont	Duote Discount Percent	Extended Amt \$47.00
Material # Part F305570B Service 4000114	es could not duplicate cond and test fire at 1/2 norm Estimate C.O.D./S Material Description X-MARK PRO 700 TRIG A GR-SHIPPING & HANDLI	cern trigger assm set scal charges. hipping and Handling C	Charges are Oty 1	NOT Include Warranty Y/N N N N	ed in this (Price/Unit \$94.00 \$17.00	Discount Percent 50% 0% 50%	Extended Amt \$47.00
Material # Part F305570B Service 4000114	es could not duplicate cond and test fire at 1/2 norm Estimate C.O.D./S Material Description X-MARK PRO 700 TRIG A GR-SHIPPING & HANDLI	cern trigger assm set scal charges. hipping and Handling C	Charges are Oty 1	NOT-Include Warranty Y/N N N N	ed in this C Price/ Unit \$94.00 \$17.00 \$23.00	Duote Discount Percent 50% 0% 50%	Extended Amt \$47.00 \$17.00 \$11.50
Material # Part F305570B Service 4000114	es could not duplicate cond and test fire at 1/2 norm Estimate C.O.D./S Material Description X-MARK PRO 700 TRIG A GR-SHIPPING & HANDLI	cern trigger assm set scal charges. hipping and Handling C	Charges are Oty 1	NOT Include Warranty Y/N N N N	ed in this (Price/ Unit \$94.00 \$17.00 \$23.00 Sub Total Est. Sales 1	Duote Discount Percent 50% 0% 50% :	Extended Amt \$47.00 \$17.00 \$11.50 \$75.50 \$2.59
Material # Part F305570B Service 4000114	es could not duplicate cond and test fire at 1/2 norm Estimate C.O.D./S Material Description X-MARK PRO 700 TRIG A GR-SHIPPING & HANDLI	cern trigger assm set scal charges. hipping and Handling C	Charges are Oty 1	NOT Include Warranty Y/N N N N	ed in this (Price/Unit \$94.00 \$17.00 \$23.00 Sub Total	Duote Discount Percent 50% 0% 50% :	Extended Amt \$47.00 \$17.00 \$11.50 \$75.50
Material # Part F305570B Service 4000114	es could not duplicate cond and test fire at 1/2 norm Estimate C.O.D./S Material Description X-MARK PRO 700 TRIG A GR-SHIPPING & HANDLI	cern trigger assm set scal charges. hipping and Handling C	Charges are Oty 1	NOT Include Warranty Y/N N N N	ed in this (Price/ Unit \$94.00 \$17.00 \$23.00 Sub Total Est. Sales 1	Duote Discount Percent 50% 0% 50% :	Extended Amt \$47.00 \$17.00 \$11.50 \$75.50 \$2.59
Material # Part F305570B Service 4000114	es could not duplicate cond and test fire at 1/2 norm Estimate C.O.D./S Material Description X-MARK PRO 700 TRIG A GR-SHIPPING & HANDLI	cern trigger assm set scal charges. hipping and Handling C	Charges are Oty 1	NOT Include Warranty Y/N N N N	ed in this (Price/ Unit \$94.00 \$17.00 \$23.00 Sub Total Est. Sales 1	Duote Discount Percent 50% 0% 50% :	Extended Amt \$47.00 \$17.00 \$11.50 \$75.50 \$2.59

TRANSMISSION VERIFICATION REPORT

TIME 12/10/2010 16:29

NAME FAX 3365487823 TFI

SER.#: BROC0J148005

DATE, TIME FAX NO./NAME DURATION PAGE(S) RESULT MODE

12/10 16:29 14808589001 00:00:24 01

ÕΚ STANDARD **ECM**

QUOTATION

Remington Arms Company, Inc. 870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

ESTIMATING REPORT

Parts/Repairs Fax.

800-243-9700

336-548-7801

www.remington.com Info@remington.com

ARAPITE AND TOTAL PROPERTY OF THE PROPERTY OF

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (4) WEEKS APITER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 15 DAYS, WE SHALL RETURN THE ITEM(S) AS RECEIVED POSTAGE DUE.


Description/Serial Number Date Received -Repair Order Number 11/19/2010 G6650217 Estimate Date -RE00211043 11/22/2010 Account # - R-Current Date -12/10/2010 Return To Customer MAGNUM PRECISION **MAGNUM PRECISION** 3828 N 28TH AVE 3828 N 28TH AVE PHOENIX, AZ 85017 US PHOENIX. AZ 85017 US (602)-200-0943 Fax Phone (H) Phone (W) **Email**

		Card No			Exp. Date	
Daytime Phone (Time To Call		Ороп Лост. <u>R</u>	Date
	· -	Notic	e: We process checks	electronically thro	ugh Check 21	
- Remission			e	Blems Bland I		
M123			T SERVICE	M123	FORWARD TO	PRODUCT SERVICE F
	VISA MC AM PO Number Daytime Phone Approval: Custo If You D	Approval: Customer Signature If You Desire Any Change Pl M123 FORWARD TO	VISA MC AMEX DISCOVER Card No. PO Number	VISA MC AMEX DISCOVER Card No. PO Number Daytime Phone () Time To Call Approval: Customer Signature If You Desire Any Change Please Use The Reverse Side For Notice: We process checks M123 FORWARD TO PRODUCT SERVICE	VISA MC AMEX DISCOVER Card No. PO Number Daytime Phone (VISA MC AMEX DISCOVER Card No

Partinician & Commence

ProblemNotes

could not duplicate concern trigger assm set screws altered can offer to replace trigger plate assm, clean and test fire at 1/2 normal charges.



BY: _____

	5153
Remington Arms Co	
14 HOEFLER AVE.	11-17-10
Ilion Ny 13357	
Enclosed is A Rem.	700 SN-66650217.
The owner of this	
that the SAFETY	
correctly and he c	
TIFLE to five by	
SAFETY Off Please	look into this
matter for us.	
	Thanks
•	magnum precision
	3828 N. 28th pre
1	Phoenix Az. 85017
(607)200 - 0943
G6650217	
Model: 700	

RE00211043

could not duplicate concern.
Trig set screws aftered. CAN
often to replace TPA, clean +
Trust fine At 1/2 Normal charges.

Quite

