Remington Arms Co., Inc. Product Service Legal Case #:4984

Inform	

Date Opened(PS) **Date Closed Incident Date** Pre Lit Obsolete **Date Opened** Lit RE# 209361 11/4/2010 11/5/2010 11/5/2010

Customer Information

Last Name Street City State Zip Contact First Name **Business** Age Type H 724-774-1251 819 Summit Ave Incident Lida J Waggoner Moraca PA 15061 E waggs819@aol.com

Incident Information

Codes Repair Est. Medical Treatment Medical Status Claims

ΡI

Cause: 4038 Could Not Duplicate Concern PD gun went off Concern:1025 Unexplained Discharge - No Mention of Safety Position

Unknown

11/15/10 Per note with rifle, "gun went off went under loading one time."cm

Firearm Information

Model/Ga. SKU Mfg. Type Serial Bbl. DOM CF/BA 700/30-06 SPR n/a A6789744 PV 6/23/1979 Remington

Accessories

Date Purchased Where Purchased KEI K MART PLYMOUTH MI **Original Owner**

U

CONCERN:FBC

Ammunition Information

Cal./Ga. SKU **UPC** DOM Mfg. Code Mfg. Type /150 Remington Other Factory Reload Concern Y 0: N

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Cash Reim. Date Cash Date Release of Claims Release Date Settlement Reimbursement Settlement **APV** APV

Per Ilion, replace TPA, clean at BLSM program price

Repair/Replacement Repair/Replacement Cost Date

> 30.23 11/15/2010

11/15/10 Per Ilion, could not duplicate concern trig assm very dirty. Check over, replace TPA, clean, test under BLSM price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		11/5/2010
Examination	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
	Description		22" 30-06 SPR
	Date Code		PV
	Bore Plugged	False	

	Bulged	False	
	Fired	False	
Barrel	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	ACTION/TRIG ASSM VERY DIRTY
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		STANDARD M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.009
Sear	Notch	Slightly Worn; Functioning	
	T	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	VERY DIRTY
Trigger	Pull	Select	5#
TITESOL	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	

•	Add Repair	Estimate Repair	Expedite Rep	air Inquiry	Repair Tools	CSR Tools	Reports	Table Maintenance	System			
		.,,	•					·		2.5		•
					Zimas							
	国 frmRE	Inquiry Rep	air Inquiry	and the second of the second	e vila od koj povjetjen (til 19. storio sipografija (til		liga villa garaga Sa Pana sa sa sa sa sa Sa Santa sa	and the second s				
	5 8 3 60 30 43	8.50 (3. 36.56.5) (1996.73	Sales of the work of	AA WALI 700	Ceole: Era Calba	r Repair						4 · · · · · ·
	Verify Repa	e: RE00209361	3006 SPRG P	oduced: 06/23/1	Center Fire Calibe 1979 SKU: 20000		man: Bruce Appro	77avis ValHold 1175/2010 11:30:4	5 7 X		te:	
֡	<u> </u>	INFORMATION	6 1		(.		oius AM				3 1.	
	12asi	Customer		● Recei	ived from Ret	um To		C Received fro	m S	, p		
	是形容的。 鄉口電影	ne: LIDA J WAGGON	CONTRACTOR CONTRACTOR		remain interpolity (AJ WAGGONER				A. Carlon		
	Address Address	9195	P0:8	oc f	1 13	SUMMIT AVE	P	O Bòx:				
	(943.06)5(060)3(522)	ity: MONACA			МО	NACA						
֡	Slat	te: PA Zip Code	15061 Co	untiy US	,	Zip Code: 1	5061	Country US			·	
					FFL: [[[[(1000 - 2000)	1
	Contact / C	andition Problems E	stamate: History / St	atus Shipping/	Billing							1
	Date	Code %	User ID. Des	c1'	Desc2	Shipping	Hold :	Current Status ApprovalHold				A. W.
	11/5/20		Travisbw Rep	air Maintenance	Status: F	☐ Interface	3000 200 S 5 3 2 2 4 1	11/5/2010 11:30:45 A	M .			
	11/5/20	······································		nate Update ediate SAP Alloca	Status: A	Parts Rec	MODEL STREET	ApproveRack				
	11/5/20			r. Repair Bench	To: Appr	☐ Passed In	2004 SEP 10 10 10 10 10 10 10 10 10 10 10 10 10	Repair Location				
	11/5/20	10 3:3 ApprovalH	BatchJob Quo	tation Control		☐ Return as ▼ ☐ Has Beer	and the same and the	Current Location ILN				
	1/20				13.4	☐ Internal F	28/5/2017/2017/2017/2017	Transfer Number				
		transpersion of the		- 13 (50 (15 (15 (15 (15 (15 (15 (15 (15 (15 (15		☐ Exclude	IAIL V			A Section 1	73	
	Repair	Search .						Refresh	Close		()	10
ĺ	<u> </u>	D. U.	4000	<u> </u>				#K _ 22		.s. A.		1.7
	T.			er ibe		Allen Comments					• .	
		Sugar Sugar					100				A.	
						+	4000	-37 T	122			
			The same of the sa				V 1.	طلقا والالا				
			# C 1							46		
		•					in our Hills of the				Marie .	
					A Section	ia was a salah sa					•••	
					PAGE I				1.128.49	Mar.		
	•											
				· ·			C E		i.n.			
									enz.			

DECETVE Nov - 8 2010 BY: 4984

Remington.

Factory Repair Instructions

(NOTE: Please	print and	complete this	form, and	then include	it with y	our firearm.)
---------------	-----------	---------------	-----------	--------------	-----------	---------------

Model Number: 700 ADL	Serial Number: A 67	789744			
Are you the original owner?: YES NO					
Name: LiDA. J WAGGONOR	Name: LiDA. T WAGGOMEN Date of Purchase: 1972				
Address (no PO Boxes):					
819 Summit AUB					
City: MORREA	State: PA Fax: NO	Zip: /5-06/			
Phone (Daytime): フォム フリチ /ユ」・ノ	Fax: NO				
E-mail Address: waqqs 819 @ aoL. C	For a second second				
Please describe your problem:	n.	·			
GUN WONT OFF	wort uno	σ <u>γ</u> .			
LUADING ONE TIME	· .				
		•••			
	and the second second				
Ammunition Information:					
Manufacturer: Rom I'mgTon	Type: 150 GR				
Other (i.e. bullet weight/type, shot size, powder):	Marine of the text	·			
		· · · · · · · · · · · · · · · · · · ·			
Handload Information:					
Powder Used:	Powder Weight:				
Case/Hull Used:	Primer Used:				
Bullet Type/Shot Size:	Reloader Used:				
Firearms Care (Cleaning and Lubrication):					
Brand of cleaning solution used: Ringle o. C					
How often do you clean the bore? (Months or Number of rounds)					
How often do you clean the action? (Months or Number of rounds)					
How often do you clean the trigger assembly? (Months or Number of rounds)					
Brand of lubricant used: RangeyTo.					

2281 PV6/ 5th How often do you lubricate the bore? (Months or Number of rounds)

How often do you lubricate the action? (Months or Number of rounds)

How often do you lubricate the trigger assembly? (Months or Number of rounds)

Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?

YES

When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?

What were the services performed?

Ship your INSURED firearm by either UPS or Parcel Post 19: 10 pcc.

REMINGTON ARMS CO., INC

A6789744

Model: 700

RE00209361

ervice Divison fler Ave Y 13357

N YOUR FIREARM OR IN THE SAME BOX WITH THE IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE ME, ADDRESS (WITH ZIP CODE), TELEPHONE AND

ng it

mage in shipping and handling. Preferably,

- ship in a firearm box. (Note: Original boxes may not be returned.)
- :: Remove all accessories from your firearm to prevent loss or damage.
- :: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.
- :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for ... damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

- :: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)
- :: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card.

Could Not duplicate concern Trog ASSM. Very Livty. Check over, Replace TPA, clear & Test Fire under Bolt Lock program for \$20.00.

Quote