1

ú

				Ren	nington Ar Product S	ms Co., Inc. Service							
					Legal Case	e #:5088							
Case Inform	nation			•									
RE#	Date O	pened	Date O	pened(PS)		e Closed	Inc	ident Da	te	Pre Li	t Lit	Obsolete	
213780		/2010	12/	13/2010	12/	/13/2010						Х	
Customer Ir													
Туре	Business	First Na	me L	ast Name		treet	City	State	Zip	Age	C	ontact	
Incident	Incident			Lopez		50th East x 150961	Ely	NV	89315	i		H 775-289-7930 F 779-289-7962	
Incident Inf	ormation												
Claims			Codes			Repair Est.	I	Medical	Treatm	ent	Medi	ical Status	
PI													
PD		Cause:4014	Defective	e Parts				Link	nown				
S C FBC		Concern:1008	Fired on	Bolt Closing				U.I.					
	ustomer cal	led in He stat	ed he had :	a FBC about a	month age	o. No damage -	No ini	iu <del>r</del> v df					
Firearm Info	ormation												
Mf	5	Туре			Ga.	SKU		Seria			DC		
Remin	C	CF/BA		710/300 WIN MA		27414		712953	54 C	A 4/	16/2006 5	5:07:02 PM	
Date Pur	chased	Where Purchased WAL MART		Accessor SCOPE B		Original Ov Y							
CONCERN	HANG FIF			30012.8	AJD	L							
						· · · · · · · · · · · · · · · · · · ·							
		on - None Defi											
•	icts Informa	tion - None D	efined										
Settlement				D	emington/7	10/CE/DA							
					-				Cash	Re	im. Date	Cash Date	
Settlen	nent	Release of (	Claims	Rele	ase Date	Reimbu	ırseme	nt Se	ttlemer		APV	APV	
Per Ilion - F n/c													
	R	epair/Replace				Date							
11/15/10 2	J. 100	\$49.5			17/2010				c.u •		.1		
		ean, test fire (		rer mon - Bol	it is miscut	at striker inder	nt. Bolt	. wiii not	iuny cl	ose. Che	ck over co	mpietely.	
Examination	n[Remington	n/CF/BA]						_					
l Dant	11 6	ub Dant	11	Cala		11			C			Т	

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date	]	12/13/2010
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4014	Defective Parts	
	Description		24" 300 WIN MAG
1	Date Code	j	СА
	Bore Plugged	False	
Barrel	Bulged	False	
'	Fired	False	
1	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	( <u> </u>	1	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5088&Type=Case

12/17/2010

1	Firing Pin	Slightly Worn; Not Functioning	STRIKER INDENT OUT OF POSITION.BOLT HEAD BROKEN
Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	]
	Ext/Eject Test	False	]
	Block Condition	Select	]
Locking	Lug Condition	Slightly Worn; Functioning	]
	Notch Condition	Select	]
Magazine	Condition	Select	]
wagazine	Box Condition	Slightly Worn; Functioning	]
	Exterior Condition	Slightly Worn; Functioning	]
Overall	Stock Condition	Slightly Worn; Functioning	]
	Fore End Condition	Select	]
Receiver	Condition	Slightly Worn; Functioning	]
Receiver	Bulged	False	
	Description		STANDARD M/710 SAFETY
Safety	Function	Like new; Functioning	]
	Sub-Assembly	Non-ISS	]
	Lift	Select	N/A
Sear	Notch	Like new; Functioning	]
	Tests	Test Fired	False
Feeding Tes	t	False	].
	Condition	Like new; Functioning	]
Triccor	Pull	Select	4#
Trigger	Altered	False	]]
	Sub-Assembly	Other Remington	]


	кц	mevau	เดเบบแทเรเ	ory sever	Expedite I	<b>K</b>	Inquiry	Repair Tool	S US	SR Tools	Reports	lable Mainter	iance	System	Location	n
			a survey of anora die	y Repair	The part of the local design of the	angen bere he	erse esterior	مىنىيەتكەر ئىرلىيەن بېرىمى مەرىپىلىرىدىنى ئىرىيەتلەر بىرىمەتلەر مەرىپىلىرىدىنى ئىرىيەتلەر بىرىمەتلەر بىرىمەتلەر	41246-2-1553 .	-)-is cession	an an an ann an an an an an an an an an	ب مربعه بینید. بهرهه به غیر به مهرو های از مرب	Satur	ngringer 🔚		
		Яера	air Number:	RE0021		Seria	1.719	95354	Mň	del 🔅	Repairman			and the second		
		Ve	ify Repair					r Fire			Status	Neŵ 12/10/2010	10:00:09	AM () - ()		
2.5	R	AD	DRESS INFO	RMATION			le Systèn Grieke Servi de Grieke	an a		ensame de la Carectería			277 W 78 V 1997		246-96 328-332	
	EE.		F 10 10 1	Customer	and the stand of the		ં	Received from	36	etum To <sub>22</sub>			Recei	ved from		
	RE	网络家体	1.642 11.65	LUIS LOPE						JIS LOPEZ	<u></u>		<u></u>	an Anto Maria		
3.4	RE	5 16 2	Address 1 Address 2:	P0 B0X 15	1991	en en	Box			) BOX 1509		PO Box	<u></u>			1 4
2	RE		City:	ELY	Canada na a Parada da da				EI	Y		<u> </u>				
	RE		State.	NV Zip	Code: _ 89315	h	Country: \U	S S	S. N	Zip Co	de: 189315	Country	US	alan ar an		
10.00	RE						120123	FFL			- dec se inte	Yallor 1		With the states		
, 1 , 1	RE	Con	N 101 - Condit	ion I Piobler	ns I Estimate	History /	Status   Sh	ipping / Billing		ana an Seo fi Sasa			16 472. 1.1 70	STORE -	ar fa sterra . Gran i sa s	
2	RE	14		1997 ( 1997 ( 1997 ( 1997 ( 1997 ( 1997 ( 1997 ( 1997 ( 1997 ( 1997 ( 1997 ( 1997 ( 1997 ( 1997 ( 1997 ( 1997 (	<b>同社学习</b> 在2017	的形式的	1. TU T 2	and the second second					ient Stati			
	RE		Date 2/10/2010 1	and the second se	User I valenti		epair Added		<u>"Désc2</u> .		ipping Hold erface Hold			0.09 AM		
1. 2.5%		- 11年末日		0 Expedi	····		rom: Check I		To:	6.000202	timate Sent		valentd			
	Ma		2/13/2010 1		Travist		epair Mainte		Status: N	lew a wea	its Received		epair Bei Iair Locat			
4			r ( ), s. t. ( j	يوائي سايي العربي. 19 في مايين ويونونه				na na na sina si na s Na si na s		1 T T	issed Inspection		CEILN S	Marine Si		
	54 		يې بې د بې درې د بې د بې درې							N. 192.29	s Been Appro	State Stat	ent Loca			•-
							第八部 江方	an a	NYZWŻ		ernal Repair -	Trar	ister Nur	iber.		
		1 <u>7</u> 1	4			6.2 ¥20			8	Section 1	clude TATC ;					
		, R	epair Se	erch							The same of a	Refr	esh	Clo	Ses	
		Star 41	AR NAME AND	18. 90 A 19. 24				1. 17 M. <b>.</b>			yar azaka ya		5×12, 53	Konter and stores	Rostandaria a	
									e ti shiri							
											intoine an					
										14 <b>.</b> .						
2	1193	N/Prod	The second s		newskieder (†			CALE OF THE	State Par	<b>**</b> *****	Támái e	Monday		etem and	10:14	Na start a star

.

•

	<del>ر انجر</del> ا سنب	C.	<u>ور المع</u>	<u>il</u>	R Second	र र र र <u>र</u> गरिः	era alt
Ņ	ß	EC	÷>	7	201	10	$\mathbb{J}$
B	3Y:			a <b>a a</b>			

5088



November 15, 2010

Luis Lopez PO Box 150961 Ely, NV 89315 Ph: 775-289-7930

Ref: # 5088

Dear Mr. Lopez,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington, H&R customer.

Sincerely, D. Fulcher Consumer Affairs Administrator Remington, H&R, Marlin Phone: 1-800-243-9700 Fax: 336-548-7872

enclosure



Bolt is miscut at struker indent. Bolt will not fully close, check over completely. Rephace BOLT ASSM, cleanst 205 fine at N/c.

# 230145

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com • (

•

Print	Reset					
Model Number: 7/0	Serial Number: 7/295354					
Are you the original ow	ner?: 🗹 YES 🖾 NO					
Name: Luis M Lopez	Date of Purchase: 6-24-06					
Address (no						
1999 50 50th Er						
City: Ely	State: NV Zip: 89301					
Phone (Daytime): 775 · 289 - 7930	Fax: 775-289-7962					
E-mail Address:(if e-mail address is provid be sent)	ed, notification of receipt and shipment will					
E-mail A	ddress:					
I would like to receive future e	e-mail updates from Remington.					
Please describe your problem and date of occurrence: IVE ONLY Shet 25 to 30 ROWDS, THREWAP, MY 300 WIN MAG MY 300 WIN MAY the INST TIME Shot WAS. 9-5-2010 I Shot 2 ROWNOS The Fristlow the Triggen Went Click DION'T FRAE Pulled of Tranget. AND ROWDD Went off 3 sec. Later. Pulled of Tranget. AND ROWDD Went off 3 sec. Later. JNO ROUND Pulled Trigger it clicked Pulled of Tranget. JNO ROUND Pulled Trigger it clicked Pulled of Tranget. JOWN All the WAY AND Lock. Tight Something is Not Right. JOWN All the WAY AND Lock. Tight Something is Not Right.						
Ammunition						
Manufacturer: Winchester	Type: 300 WIN MAG					
Other (i.e. bullet weight/type, shot size, powder): 180 gr. Power Point						
Handload Information:						
Powder Used: "'R" 19	Powder Weight: 75 an.					
Case/Hull Used: Winchester	Primer Used: CCI Magsum					
Bullet Type/Shot Size: 165ga XBT	Primer Used: <u>CCI Magnum</u> Reloader Used: <u>Honnaby</u>					
BARNES						
Firearms Care (Cleani	ng and Lubrication):					

• `.

Brand of cleaning solution used: Outers	
How often do you clean the bore? (Months or Number of	
rounds) 15-to 20 Rounds	
How often do you clean the action? (Months or Number of rounds)	
How often do you clean the trigger assembly? (Months or Number of rounds) 15+0 この Reuwings	
Brand of lubricant used: Quters	
How often do you lubricate the bore? (Months or Number of rounds)	
How often do you lubricate the action? (Months or Number of rounds)	
How often do you lubricate the trigger assembly? (Months or Number of rounds)	
Have you reviewed the cleaning and maintenance recommendations on our web s in our owners manual? > YES VANO	site or
When was the last time that your firearm was serviced by a Remington authoriz repairman/gunsmith?) $\frac{N/A}{}$	ed
What were the services performed?)	
Ship your INSURED firearm by either UPS or Parcel Post to:	
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357	
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OF THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LA YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE) TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.	W. IF
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and hand Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments with proper	U

## return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your

carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

8872

VISA REDACTED EXP. Date 3-201

http://www.remington.com/asp/factory\_repair\_form.asp



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

## ARS LABEL REQUEST FORM

DATE:		11/15/2010	REQUESTED BY:	Dell
QUANTITY:		1	WEIGHT PER PACK	A(10 lbs
PLEASECHECKONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXXX
DESCRIPTION:	Ref# 5088 Rifle			

## LABEL INFORMATION

MAIL LABEL TO: Luis Lopez PO Box 150961 Ely, NV 89315 Ph: 775-289-7930

RETURN ITEM TC Remington Arms Attn: Product Service Ilion, NY

APLEASE COMPLETE ALL PARTISION THIS FORM AND SEND TO THE MEDIA COORDINATOR

4XX596 NOV 15 SVC GNDCOM TRACKING# 124XX5969 REF 1:LUIS LOPEZ/CD REF 2:5088/RIFLE	0663765	WT 10.01	CURR USD LBS	1 OF 1
HANDLING CHARGE 0.0 SINGLE-PIECE PUB RF DV 0.00 DC 0.00 AH 0.00 TOT PUB CHG 11.74		GS: 0.00 0.00 0.00 PUB+HAN	RS SD SP	T/P USD 0.50 0.00 0.00 11.74



