Remington Arms Co., Inc.
Product Service
Legal Case #:6691

Case Information

 RE#
 Date Opened
 Date Opened(PS)
 Date Closed
 Incident Date
 Pre Lit
 Lit
 Obsolete

 243645
 10/14/2011
 10/17/2011
 10/17/2011

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Incident Terry Foster 10246 County Rd 1289 Tyler TX 75709 E terafo@suddenlink.net

Incident Information ...

Claims Codes Repair Medical Medical Est. Treatment Status

ΡI

PD Cause:4006 Al

Cause: 4006 Altered Adjustments or

Components Unknown

release Concern:1007 Fired on Safe Release

С

10/26/11 Per note on SR, claims firearm discharged when flipping from safety to fire.cm

Firearm Information

Mfg.

Type

Model/Ga.

SKU

Serial Bbl. DOM

Remington

CF/BA

700/3006 SPRG

n/a

6683129 EX 11/7/1973

Date Purchased

Where Purchased

Accessories

Original Owner

0063129 EX 11///19/3

MORRIS DICKSON SHREVEPORT LA TWO PIECE BASE

U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Date Date

APV APV

Replace TPA, clean and test fire under BLSM program price

Repair/Replacement Repair/Replacement

Cost

Date

45.40

10/26/2011

-

10/26/11 Per Ilion, trigger assm dirty, rusty and set screws altered. Replace TPA, clean and test fire under BLSM program price of \$20 + shipping.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment	
	Examiner		B.TRAVIS	
	Exam Date		10/17/2011	
Examination	Product Type		RF	
	Action Type		A	

httn://cnc03an13.700/ncaann/PrintDienlaw acrevID=6601&Tune=Cace

10/26/2011

	Assigned To		T.NAGLE	
Cause	4006	Altered Adjustments or Components	IMPROPER MAINTENENCE	
	Description		22" 3006 SPRG	
	Date Code		EX	
	Bore Plugged	False		
	Bulged	False	1	
Barrel	Fired	False		
	Fired while Obstructed		-	
	Muzzle/Crown Condition	Slightly Worn; Functioning		
Bolt	Firing Pin	Slightly Worn; Functioning		
	Shroud	Slightly Worn; Functioning		
	Face	Slightly Worn; Functioning		
	Handle	Slightly Worn; Functioning		
	Stop	Worn; Functioning		
Extractor	Condition	Slightly Worn; Functioning		
	Cut Condition	Slightly Worn; Functioning		
	Ext/Eject Test	False		
Locking	Block Condition	Select		
	Lug Condition	Slightly Worn; Functioning		
	Notch Condition	Select		
Overall	Exterior Condition	Slightly Worn; Not Functioning		
	Stock Condition	Worn; Functioning	SCRATCHES,MARS	
	Fore End Condition	Select		
Receiver	Condition	Slightly Worn; Functioning		
	Bulged	False		
Safety	Description		M/700 BOLT LOCK SAFETY	
	Function	Like new; Funcționing		
	Sub-Assembly	Non-ISS		
	Lift	Select	.007	
Sear	Notch	Slightly Worn; Functioning	DIRTY	
	Tests	Test Fired	False	
Feeding Test	10303	False		
Trigger	Condition	Slightly Worn; Not Functioning	RUSTY,DIRTY TRIG NOT RETURNING PROPERLY WILL FOLLOW DOWN	
	Pull	Select	3.5#	
	Altered	True	SET SCREWS ALTERED	
	Sub-Assembly	M/700 Bolt Lock		

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6691&Type=Case

10/26/2011

	<u> </u>	 	
Non-Remington Components	Description	TWO PIECE BASE	

Service Request

Remington Service FO Box 700

Date of Request:

Date Printed:

10/10/2011

10-10-2011

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700.F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service.

PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

Service Request Number

Serial Number / Description

SR00000546

6683129

Model 700

Customer: TERRY FOSTER 10246 COUNTY RD 1289

TYLER, TX 75709 US

Destination:

Arms Services 14 Hoefler Ave Ilion, NY 13357 US

Email:

Email: terafo@suddenlink.net

-Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

ME46 - RMA SERVICE REQUEST

Service Request Section

Claims firearm discharged when flipping from safety to fire.

Parts And Service Details

Material

Type

Description

Qtv Needed

Warranty

Disc Amount



T.A. dirty, rusty + set screws Altered. Replace TDA, & work + post Rine under BLP Controlo + ships

Sub Total: Est Sales Tax: .00 .00

Grand Total:

\$.00

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the









