.

Remington Arms Co., Inc.	
Product Service	
Legal Case #:7061	

			Le	gai Case #:/061					
Case Informat RE #		Dat		-	Incident D	-+	Dra I it	T :+	Obsolete
ке <i>#</i> 249790	12/12/2011		-	12/13/2011	Incluent D		f it Lu	Lu	Obsticie
Customer Info	ormation								
Туре	Business Fir	st Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Larry	Weed	7103 Goats Hw	y Manistee	MI	49660		
Incident Infor	mation								
	aims		Codes		Repair Est.	Medical	Treatme	nt Me	dical Status
PI		C		C	_				
PD S Fired on C	Date Opened 12/12/2011 Date Closed 12/13/2011 Incident Date Pre Lit Lit Obsolete 12/12/2011 12/13/2011 12/13/2011 12/13/2011 12/13/2011 Business First Name Last Name Street City State Zip Age Contact Business First Name Last Name Street City State Zip Age Contact aution Larry Weed 7103 Goats Hwy Manistee MI 49660 Age Contact aution Cause:4006 Altered Adjustments or Components Unknown Street Street E0307592 LR 2/7/1997 safety release Concern:1007 Fired on Safe Released.un Modd/Ga. SKU Serial Bbl. DOM n CYBA 700/300 WIN MA 2/7482 E0307592 LR 2/7/1997 sed Where Purchased Accessories Original Owner Settlement Release of Claims Release Date Settlement Settlem								
	ote on SR, rifle fire	d when the	safety was released.	cm					
Firearm Infor	mation								
Mfg.		Т	уре	Mode	/Ga.	SKU	Seri	al B	bl. DOM
Remingto		CI	F/BA	700/300 V				592 L	R 2/7/1997
Date Purcha					ories Origi		r		
CONCERN: I		MOUNTAI	N ELK FOUNDAT	ION		U			
Settlement Settlement Can offer to and test fire 1/11/12 Per II	ettlement o replace TPA, clear e at 1/2 normal cost ion, trigger assm di	Relea n Repair rty and set s	ase of Claims r/Replacement H Cost	Release Date Repair/Replacemen Date	t	^{nt} Settle	ment D	ate AP	
	· · · · · · · · · · · · · · · · · · ·								
Part	Sub-Part		Code			Comm	ent		
T					3/2011		····		
Examination					<u> </u>	ne:	<u></u>		
0					AGLE				J
Cause			ered Adjustments o						
					SUU WIN MAG				
	<u></u>			Ľĸ					J
Damat			·····						
Barrel									
			5C						
			hthy Warne France						
	Shroud	تو ا							
i l	ISHLONG	10118	ան անդանը հայնել	mig					

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7061&Type=Case

1/11/2012

•

		-	·
	Face	Slightly Worn; Functioning	
Bolt	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
[Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
·	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.013
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	t	False	
	Condition	Slightly Worn; Not Functioning	DIRTY. TRIG NOT RETURNING WILL FOLLOW DOWN
Trices	Pull	Select	3#
Trigger	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7061&Type=Case

1/11/2012



Remington Service

PO Box 700



r2/

3[#]

•013

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

Service Request Number	Serial Number / Description	7061	Date of Request:	11/14/2011
SR00003623	E6307592	1	Date Printed:	11/29/2011
Customer:	Model 700 RIFLE Caliber: 300	Destination	·	
LARRY WEED	· •	Arms S	ervices	
7103 GOATS HWY			fler Ave	
MANISTEE, MI 4966	0 05	1110 n , f	NY 13357 US	
Email:		Email:		
	e item(s) will be evaluated by our repairman to determ	ine if it is covered under our	warranty policy. If it is your firearr	n will be repaired and
returned. If not, you will be c	ontacted with an estimate before work is performed.			, * · ·
· · ·			н 	14
	· ·		~	
			an contractor de la contra	
Reason For Return				
M240 - BOLT LOCK SA	FETY MODIFICATION			
Service Request Section				
PER CONSUMER, RIFL	E FIRED WHEN THE SAFETY WAS RELEAS	SED.		
	· · · ·		· · ·	المبيع مستعصفي يتحاجات
	·			
Parts And Service Detail				
Material Type	Description	Qty Wai Needed	ranty Price	Disc Amount
a a se				
i	-00		<i>.</i>	
E63075	572			
			1 1 1 -	0 11-0
Model: 70	Ø	7.1.0	firsty + set scree fren to ny the live at 1/2 Non	ws Alfeed.
			Pland another	TPA, Lleanit
		CANOI	- ren roing in -	al et
		Tost	Live At 1/2 NON	NY91 4051.
		·		
REU	0249790		Qual	٥
			-0-00	
. · ·	e e e e e e e e e e e e e e e e e e e			
이가 한번 도망이 있다. 	Ref March 19, 1992 March 19, 1997	mir.	GEIVED	
		N C		
		<u> </u> 肌 nF		
		BY:	建设口口有多些动物的变化成本的现在分词	
THIS IS NOT AN INVOICE.	This is a pre-estimate to repair, recondition, or replace	·	Sub Total:	.00
	rsation with our representative.		Est Sales Tax	
			Grand Total	\$.00







