

Remington Arms Co., Inc.
Product Service
Legal Case #:8151

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
288901	11/12/2012	11/13/2012	11/13/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Michael	Wight	12721 Whisper Bend Dr.	Draper	UT	84020		H 801-699-8701 E mikewight1@hotmail.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S FBC	Concern:1008 Fired on Bolt Closing			
C				

SR# 33423 - Customer stated that rifle discharged when pushing the bolt handle forward & rounds are difficult to load into chamber. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/223 REM	84370	G6831210	LD	3/23/2009 4:52:13 PM
Date Purchased	Where Purchased	Accessories	Original Owner			
	CABELA S INC/WAREHOUSE /		U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Replace TA & test @ n/c						

Repair/Replacement Cost	Repair/Replacement Date
\$51	

12/3/12: Per Ilion - Could not duplicate concern. To restore confidence in rifle, will replace TA, check over & test @ n/c. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		11/13/2012
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 223 REM VTR
	Date Code		LD
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		XMP SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.012
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	3#
	Altered	False	
	Sub-Assembly	X-Mark Pro	

frmREInquiry - Repair Inquiry

Repair Number: RE00288901

Serial: G6831210 Model 700 RIFLE Caliber: 223
REM Produced: 03/23/2009 SKU: 84370

Repairman:

Verify Repair

Status: New 10/30/2012 5:09:51 PM

8151

ADDRESS INFORMATION

Customer

Received from

Return To

Received from

Name: MICHAEL WIGHT

MICHAEL WIGHT

Address 1: 12721 WHISPER BEND DRIVE

12721 WHISPER BEND DRIVE

Address 2: PO Box:

PO Box:

City: DRAPER

DRAPER

State: UT Zip Code: 84020 Country: US

UT Zip Code: 84020 Country: US

FFL: 01011900

Contact / Condition Problems Estimate History / Status Shipping / Billing

Contact Information

Phone:

Fax:

Email: mikewight1@hotmail.com

Comments:

Received Condition

Good

Condition
NotesCSR Notes: discharged when pushing
the bolt handle forward.
Rounds are difficult to
load into chamber.

Accessories Received

Code	Desc	Qty
A007	With Stud	3

could not dup. concern
to restore confidence in
Rifle will rep. TPA, checkoube
+ test at H/C #260974

Refresh

Close

G6831210

Model: 700



RE00288901

LD 2/09
3#
22"
.012





