PrintDisplay Page 1 of 2

Remington Arms Co., Inc. Product Service Legal Case #:8087

					ise #:8087					
Case Infor	mation			· ·						
RE# Date Opene		-	d Date Opened(PS)		Date Closed		Incident Date		Pre Lit Lit Obsolet	
286957		/2012	10/26/2012	1	0/26/2012					X
Customer I	Information									
Type	Business	First Name	Last Name	Street	City	State	Zip 2	Age	Conta	ict
Incident		Gilbert	Morisak	7853 CR1	Hallettsville	TX	77964	E cdr	m411@g	gmail.com
Incident In	formation									
	Claims		. Co	odes		Repair Est	. Med	ical Treatmer	it Me	dical Status
PI						•				
PD E:			use:4038 Could	-				Unknown		
C Fired	d on safety re	elease Co	ncern:1007 Fired	on Safe Relea	se					
	r note on SR.	gun fired wher	flipping the safet	v to fire.cm						
							#*************************************			
Firearm In		_			_					
Mf	-	Type	- -				SKU Serial Bbl. DOM			
Remington CF/BA Date Purchased Where Purchased				600/222 REM n/a 6650516 AY 3/ Accessories Original Owner					Y 3/1/1974	
Date I ui	cuaseu v	where rurchas			OM HALF RIN		riginai (U	Jwner		
CONCERN	N: FSR		SCOLL	JABE, BOTT	SWITALI KIN	GB	u	•		
Settlement				Remington	/600/CF/BA					
	Settlement	1	Release of Claims	Rele	ase Date	Reimburse	ment s	Cash R ettlement	eim. Dat APV	te Cash Dat APV
	replace TPA, SM program									
		Re	epair/Replacemer		Replacement					
			Cost 26.81		Date /6/2012					
11/6/12 Per	r Ilion, could	not duplicate c	20.61 oncern. Trigger as			lace TPA.	clean, tes	t at BLSM pro	gram pri	ice.cm
			36 1						5 F	
Examinatio	on[Remington	n/CF/BA]								
	Part		Sub-Part		Code		<u>. </u>	Comm	ent	
		Exam	iner		· · · · · · · · · · · · · · · · · · ·	B	.TRAVI			
		Exam	Date			1	0/26/201	2		
Examination		Produ	Product Type			R	F			
		Actio	п Туре			Ā				
		Assig	ned To			. [T	.NAGLE			
Cause		4038		Could N	ot Duplicate Co	ncem R	IFLE HA	S AN UPDA	TED TPA	A
		Descr	iption			1	8.5" 222	REM		
		Date	Code			[A	Υ			
			Plugged	False						
Barrel		Bulge	:d	False						

Fired False

Fired while Obstructed Slightly Worn; Functioning

Slightly Worn; Functioning

Firing Pin

İ	Shroud	Slightly Worn; Functioning	╡ !
			=
Bolt	Face	Slightly Worn; Functioning	╡
	Handle	Slightly Worn; Functioning	<u>-</u>
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
,	Notch Condition	Select	
	Exterior Condition	Worn; Functioning	
Overall	Stock Condition	Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description		BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.009
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
	Condition	Slightly Worn; Functioning	VERY DIRTY,STICKY
Trican	Pull	Select	5#
Trigger	Altered	False	
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		SCOPE BASE, BOTTOM HALF RINGS

Service Request

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801 www.Remington.com

,00°

serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCT YOUR RETURN. This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This

SR00030079

Service Request Numberial Number / Description

6650516 Model

Customer: GILBERT MORISAK

7853 CR 1 HALLETTSVILLE, TX 77964 US

Email: cdrm411@gmail.com

Date of Request 09/25/2012 Printed09/25/2012

Destination: Arms Services 14 Hoefler Ave Ilion, NY 13357 US

Fmail:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your fireaux will be rep returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M240 - BOLT LOCK SAFETY MODIFICATION

Service Request Section

Gun fired when flipping the saefty to fire

Parts And Service Details

Material Type Description

Warranty

Price Disc Amount

遠6650516

could not dyp. concern.
Th. verydinty + sticky. replace
The cleans test under BLP
for \$ 20. t.