Remington Arms Co., Inc.
Product Service
Legal Case #:7786

			Legal Case #:77	86					
Case Informa	ation								
RE # 273743	Date Opened 7/10/2012	Date Opened(PS 7/16/2012	5) Date Clos 7/16/201		Incide	nt Date	Pre I	Lit Lit	Obsolete X
Customer Inf	formation								
Type Bu	siness First Name	Last Name	Street	City	State	Zip	Age	Cont	tact
Incident	Michael	Reiter 59	23 Olive Ave SE	Auburn	WA	98092	En	H 253-31 areiter6@	5-1378 comcast.net
Incident Info	rmation								
Clai	imīs	Cod	les	р	lepair l	Est.	Medica Treatme		Medical Status
PI		•							
PD	Cause:	4006 Altered Ad Componen	justments or				Unknow		
S bolt	en closing Concer	n:1008 Fired on B					Ulkilow	11	
С			J						
	ote with rifle, 600 re								
not touched.	This was the 2nd sho	ot of the day. 1st sh	ot was normal; sat	fety and t	rigger	were no	t manipula	ted betwe	en shots.cm
Firearm Info	rmation								
Mf		Туре	Model/Ga.		SK	U	Seria	ıl Bbl.	DOM
Remin	~	CF/BA	600/308 WIN		2000		7401	3 ON	7/1/1966
Date Pur	chased Who	ere Purchased	Accessories	Oı	iginal	Owner			
					U				
CONCERN:	FBC								
Ammunition	Information - None	Dofinad					 .		
	ts Information - None								
Settlement	os miormación - ivol	io Bennea							
]	Remington/600/Cl	F/BA					
							Cook	Rein	n. Cash
Settle	ment Rele	ease of Claims	Release Date	Rei	mburs	ement	Cash Settlemen	it APV	
	eplace TPA er recall at no								
Cita	•	ir/Replacement	Renair/Renlacem	ent					
	жера	Cost	Date						
		43.8 1	7/23/2012						
7/23/12 Per I	lion, replace TPA ar	d test upder recall	at no charge.cm						
Examination	[Remington/CF/BA]								
Part	Sub-Part		Code				Commo		
Fart	Examiner		Code		RAVI:	2	Comme	<u> </u>	
	Exam Date				6/2012				
Examination				RF	JIZ01Z				
	Action Type			A					
	Exchon Type			<u>~</u>				 	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7786&Type=Case

7/23/2012

PrintDisplay Page 2 of 2

	Assigned To]	T.NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		18.5" 308 WIN
	Date Code		ON
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		_
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	.] · · ·- ·
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning]
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
Cafat.	Description		M/600 BOLT LOCK SAFETY
Safety	Function	Slightly Worn; Functioning	
	Lift	Select	.003
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING WILL FOLLOW DOWN
	Pull	Select	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	Other Remington	

7786

Model Number: Serial Number: 74013

Name:

Michael Reiter

Date of Purchase:

Summer 2011

Address (no PO Boxes):

5923 Olive Ave SE

City:

State: WA

Zip: 98092

Phone (Daytime):

253-315-1378

Fax: N/A

E-mail Address: mreiter6@comcast.net

Please describe your problem:

Remington 600 Recall Repair needed. Rifle discharged upon rotating the bolt to the locked position. Trigger was not touched. This was the 2nd shot of the day. 1st shot was normal; safety and trigger were not manipulated between shots.

Rephacited + Test univer recall At N/c #230145

260 characters left

74013

Model: 600

EF00273743

rearm, contact the Repair Center nated repair time.

LIVE OR SPENT SHELLS IN SAME BOX WITH THE ION OF FEDERAL LAW. IF YOU VT SHELLS PLEASE SEND AGE AND INCLUDE NAME, TELEPHONE AND MODEL AND

SERIAL NUMBER OF YOUR FIREARM.

:: Record the serial number of your firearm before sending it.

:: Pack your firearm for safety and to prevent further damage in BY: shipping and handling. Preferably, ship in a

firearm box. (Note: Original boxes may not be returned.)

- :: Remove all accessories from your firearm to prevent loss or damage.
- :: Ship your INSURED firearm by either UPS or Parcel Post.

ECEIVII JUL 1 9 2012

CHEMO10 5:00 ANA

F٦

Remington Service



Madison, NC 27025-0300 Parts and Repairs: P:800-243-9300 F 336-548-7801 www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted.	h
serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DO	C1
YOUR RETURN.	

Service Request Numberial Number - Description \$R00022866 74013		Date of Date	Request£6 26 . Printed36 26 .	2012
Model Customer: -MCHAEL REITER -S923 OLIVE AVE SE AUBURN, WA 98092 US	Destination: Arms Services 14 Hoefler Ave Ilion, NY 133	č		
Email: mreiters & comcast.net	Email			
Your request for service on the item(s) will be evaluated by our repain returned. If not you will be contacted with an estimate before work is	nan to determine if it is covered und performed.	jet om wat	ranty policy. I it is	your fiream will b
Reason For Return M240 - BOLT LOCK SAFETY MODIFICATION				
Service Request Section				
Ports And Service Details Material Type Description	Qty Warranty Needed		Price Disc	Amount
			Total: Sales Tax:	.00
		Gr	and Total:	\$.00

of7