PrintDisplay Page 1 of 2

## Remington Arms Co., Inc. Product Service Legal Case #:7564

			Legal	Case #:756	4					
Case Information										
RE# Date Opened		Date Opened(PS)		Date Closed		Incident Date		Pre Lit	Lit	Obsolete
264222 4/9/2	012	4/10/2012	2	4/10/2012	2					Х
Customer Information			<b>.</b>		C:	<b>.</b>	<b></b>	<b>4</b>	_	
Type Business	First Name	Last Name	Street		City	State	•	Age		ntact 578-9776
Incident	Harry	Taylor	67 Sydney	Dr. Ess	sex Junction	VT	05452	]		l@aol.com
Incident Information							•			
Claims		Codes		R	epair Est.	Med	lical Trea	atment	Med	ical Status
PI										
PD Ca	ruse:4038 Co	ould Not Duplic	ate Concern				Unknow	m		
S FSR Co	oncem:1007 Fi	red on Safe Rele	ease				Olkilow			
SR# 15191 - Reason for off. df	Return: Bolt L	ock Safety Mod	dification, Ser	vice Reques	st Section: Fi	ring pin	sometime	es drops w	hen safe	ty is flipped
Firearm Information										
Mfg.		Туре	Mo	del/Ga.		SKU		Serial	Bbl.	DOM
Remington		CF/BA	600/3	308 WIN		п/а		7539	AL	3/1/1964
Date Purchased	Wher	e Purchased		essories PE BASE	Orig	inal Ow U	ner			
CONCERN: FSR										
Ammunition Information	n - None Defin	eđ							-	
Other Products Informat										
Settlement										
			Remingt	on/600/CF/	BA					
Settlement	Releas	e of Claims	Release	e Date	Reimburse	ement	Cash Settleme		m. Date APV	Cash Date APV
Per Ilion - Repair @ n. under recall	/c									•
•		Replacement Cost	Repair/Rep Da							
4/16/12: Per Ilion • Coul	d not duplicate	\$44 concern Repla	ce TA, clean	& test fire u	ınder recall (	g n/c. df				
Examination[Remington	/CF/BA]	:					<del>,</del>	-		
		<del></del>						<del> </del> .	:	
Part		Sub-Pai	п		Code			Co	mment	

Part	Sub-Part	Code	Comment		
	Examiner		B.TRAVIS		
Examination	Exam Date		4/10/2012		
	Product Type		RF		
	Action Type		A		
	Assigned To		T.NAGLE		
Cause	4038	Could Not Duplicate Concern			
Barrel	Description		18.5" 308 WIN		
	Date Code		AL		
	Bore Plugged	False			
	Bulged	False			
	Fired	False			
	Fired while Obstructed				
	Muzzle/Crown Condition	Slightly Worn; Functioning			

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7564&Type=Case

5/3/2012

PrintDisplay Page 2 of 2

	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
RECEIVE	Bulged	False	
Safety	Description		M/600 BOLT LOCK SAFETY
Salety	Function	Like new; Functioning	
	Lift	Select	.002
Sear	Notch	Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	1686	False	
	Condition	Slightly Worn; Functioning	
Trigger	Pull	Select	4#
Inggo	Altered	False	
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		SCOPE BASE

## Service Request

Remington Service PO Box 700

Parts and Repairs: P:800-243-9700/F:536-548-7801

Madison, NC 27025-0700 www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideling for our Service Department to address your specific concerns and provide you with accurate and complete service. INCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number SR.00015191

Serial Number / Description

Model 600 Center Fire Cald

Customer HARRY TAYLOR 67 SYDNEY DR

ESSESJUNCTION, VI 05452 US

Date of Request: 03/14/2012 Date Printed: 03/23/2012

Destination:

Arms Services 14 Hoefler Ave

Ilion, NY 13357 US

Email: hjimtayl@aol.com

Your request for service on the item(s) will be evaluated by our repairmen to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

MD40 - BOLT LOCK SAFETY MODIFICATION

Service Request Section

FIRING PIN SOMETIMES DROPS WHEN SAFETY IS FLIPPED OFF.

Parts And Service Details

Description Or Warranty Needed

Disc Amount



APR 1 6 2012

could not Lyp. concerns

Applice TPA, cleant Tost

under (UEA) 1 A+ 14/c

THE IS NOT AN ENVOICE. This is a pre-estimate to repair, recondition, or replace the

#730N5

Sub Total:

. 80

Est Sales Tax:

.00

Grand Total:

\$.00