Remington Arms Co., Inc. Product Service Legal Case #:7200

Inform	

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 251458 12/21/2011 1/5/2012 1/5/2012

Customer Information

Contact Type **Business** First Name Last Name Street City State Zip Age Mike Dickerson 659 County Rd 340 Parshall CO 80468 E and msd@yahoo.com Incident

Incident Information

Claims Codes Repair Est. **Medical Treatment Medical Status**

PI

PD Cause: 4038 Could Not Duplicate Concern S

Unknown Concern: 1023 Delayed Firing - Firearms

C Delayed firing

1/24/12 Per note on SR, customer has had two occasions with delayed firing of the rifle. Approx 2 sec. Once the firing pin fell the 2nd time it was like the trigger jammed. While attempting to safe the rifle it discharged.cm

Firearm Information

Mfg. Type Remington CF/BA

Model/Ga. 770/300 WIN MA

SKU 85658

Serial Bbl. M71586342 AE 3/31/2010 9:32:14 AM

DOM

Date Purchased

Where Purchased GANDER WAREHOUSE #1/Leban

Accessories SCOPE BASE

Original Owner

U

CONCERN: DELAYED FIRING

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/770/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Cash Settlement Reim. Date Cash Date APV APV

Per Ilion, fit new TPA, clean and test fire at no charge

Repair/Replacement Repair/Replacement

Cost

Date

41.15

1/24/2012

1/24/12 Per Ilion, could not duplicate concern. Some light rusting on trigger assm. As a gesture of goodwill, will fit new TPA, clean and test fire at no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/5/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 300 WIN MAG SS
	Date Code		AE
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7200&Type=Case

1/24/2012

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Condition	Select	
Magazine	Box Condition .	Slightly Worn; Functioning	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	GRIP CAP MISSING
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Keceiver	Bulged	False	
Safety	Description		M/770 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	10313	False	
Trigger	Condition	Slightly Worn; Functioning	LITE RUSTING
	Pull	Select	4#
	Altered	False	
	Sub-Assembly	Other Remington	

arts and Repairs: P:800-243-9700/F:336-548-7801 www.remington.com

s document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted ye as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS I 541

UR RETURN.

:vice Request Number / Description

00005718

M71586342

Model 770 RIFLE Caliber: 300

stomer: MIKE DICKERSON 659 COUNTY RD 340 PARSHALL, CO 80468 US

Email: and_msd@yahoo.com

Date of Request 12/05/2011 Printedi 2/05/2011 Date

Destination: 14 Hoefler Ave Ilion. NY 13357 US

Email:

our request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be umed. If not, you will be contacted with an estimate before work is performed.

eason For Return 990 - FRNG PIN

rvice Request Section

istomer has two occasions with delayed firing of rifle, approx. 2 seconds. Once the firing pin fell he second time it was like the trigger jammed. While attempting to safe the rifle it discharged.

irts And Service Details

iterial

Type

Description

Needed

Warranty

Price Disc Amount

586342

could not deplicate concern Some lite pusting ON TA. AS A Good-Will Gesture Will fit a New TPA, clean+ Tost Rine At N/C

Sub Total: Est Sales Tax: .00 .00

Grand Total:

\$.00





