Remington Arms Co., Inc. **Product Service** Legal Case #:7195

Case Information

RE# **Date Opened**

1/13/2012

Date Opened(PS) 1/4/2012

Date Closed

1/16/2012

Incident Date

Pre Lit Lit Obsolete

Customer Information

Type Business

First Last Name Name

Street

City State Zip Age

Contact

Reporter

253940

Blackland Gun Works

Blackland Gun W

6900 Cty Rd 101

Taylor TX 76574

W 512-365-1306 E

blacklandguns@eccwireless.com

Incident Information

Claims

- Codes

Repair Est. Medical Treatment Medical Status

PΙ

PD

Cause:4015 Improper Maintenance

Concern:1008 Fired on Bolt Closing

Unknown

1/4/12 Fired on bolt closing.cm

S Fired on bolt closing

Firearm Information

Mfg.

Type CF/BA Model/Ga.

SKU

Bbl. DOM Serial

Remington **Date Purchased**

Where Purchased

700/3006 SPRG Accessories

n/a

A6655848 DQ 9/26/1978

SPT SOUTH SHREVEPORT LA TWO PIECE BASE

Original Owner

U

CONCERN: FBC

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Cash

Reim. Cash

Settlement

Release of Claims

Release Date

Reimbursement

Settlement

Date Date APV APV

Per Ilion, replace TPA, clean, test fire at BLSM program price

Repair/Replacement Repair/Replacement

Cost

Date

30.40

1/18/2012

1/4/12 Emailing ARS.cm 1/18/12 Per Ilion, trigger and trigger pin rusted and trigger is frozen to side plates. Replace TPA, clean, test fire at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment	
Examination	Examiner		B.TRAVIS	
	Exam Date		1/16/2012	
	Product Type		RF	
	Action Type		A	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7195&Type=Case

1/18/2012

	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
	Description		22" 3006 SPRG
	Date Code	Ī	DQ
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	<u> </u>
	Fired while Obstructed		_
	Muzzle/Crown Condition	Slightly Worn; Functioning	· ·
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	SLUGGISH
	Condition	Slightly Worn; Functioning	_
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select]
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select] .
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver .	Condition	Slightly Worn; Functioning] .
•	Bulged	False]
	Description]	M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning]
	Sub-Assembly	Non-ISS	
	Lift	Select	.007
Sear	Notch	Slightly Worn; Functioning	
	Toots	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG AND PIN RUSTED TRIG IS FROZEN TO SIDE PLATES
	Pull	Select	N/A
	Altered	False	Ť

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7195&Type=Case

1/18/2012

	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

Quotation

Remington Service PO Box 700

Madison, NC 27025-0700

Estimating Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Number RE00253940	A66	ial Number / Description i55848 del 700 Center Fire Caliber: 30 -06 sprg	Îh		Date Reco Estimate Date Prin	Date:	01/13/20 01/16/20 01/24/20	12
Customer: BLACKLANI 6900 CTY RI TAYLOR, T	-	cs .	Re	eturn To: BLACKLAND 6900 CTY RD TAYLOR, TX	101	S		
Please Circle One VISA MC Open Account	DISCOVER	Card NoPO Number:		Ex	p.Date			:
If you desire	e any change, p	Tim lease use the reverse side for your common the state of the reverse side for your common the state of the	ents and mark this Problems Found		Date:		1,22	
-trigger and trigger hipping	pin rusted,trig	Technic ger is frozen to side plates replace trigge	ian Comments : r plate assm,clear	and test gfire un	der bolt lock p	rogram fo	r \$20.00	+ s
Material F305572B 4000114 4000116	Type Part Service Service	TIMATE (note: C.O.D./Shipping and H Description 700 X-MARK PRO TRIG ASSB LH BI GR-SHIPPING & HANDLING (GUN F GR-LABOR	Qty Needed ACK (OS) 1	Warranty	Qty From Inv 1	Price .00 17.00 1.00	Disc 0 0 0	.00 17.00 20.00
4000119	Service	GR-TEST	1	Warranty	1	.00	0	.00

Sub Total: Est Sales Tax: 37.00

2.50

\$39.50 Total

Service Request

Remington Service PO Box 700

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSÉ THIS DOCUMENT WITH YOUR RETURN.

D

Z

Serial Number / Description Service Request Number SR00008313 A6655848

Date of Request: 01/04/2012

Date

Printed:

01/04/2012

Customer:

BLACKLAND GUN WORKS 6900 CTY RD 101 TAYLOR, TX 76574 US

Destination:

Arms Services 14 Hoefler Ave Ilion, NY 13357 US

Email: blacklandguns@eccwireless.com

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Parts And Service Details

Description

Qty Needed Warranty

Price Disc Amount

A6655848

Model:

Trig + Trig piw rusted + TRIQ IS FROZER to SIDE PHATES. Lythice TOA, clean YEST fine under BCP for \$ 20.+

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total: Est Sales Tax: .00

.00

NOTE: Flease complete and print this form, and then include it with your firearm.

Model Number: 700	Serial Number: A 6 6 5 5 8 4 8						
Are you the original owner?: YES NO							
Name:	Date of Purchase:						
BLACKLAND GUN WORKS							
Address (no PO Boxes): ERIC WINKELMANN - (
City: TAYLOR, TX 765							
Phone (Deytime):	Fexi						
E-mail Address:(if e-mail address is provided, notification	on of recelpt and shipment will be						
sent)							
E-mall Address:							
Would-like to receive tuture e-mal-updates from P.	ernington.						
Please describe your problem and date of occurrence	:ε;						
	hor chase						
BOLT							
500 1 characters left	<u>郑</u> · · · · · · · · · · · · · · · · · · ·						
Ammunition information:							
Manufacturer:	Type: 1.						
Other (i.e. builet weight/type, shot size, powder):							
Owier (i.e. Bower warging type, Singreize, powder).							
Handload Information:	de la constantina della consta						
Powder Used:	Powder Weight: 3						
Case/Hull Used:	Primer Used:						
Bullet Type/Shot Size:	Raloader Used:						

Please send your firearm back via a traceable method of shipping to the address below.

This Service Request number is only valid for this return.

Please follow these guidelines:

- Include a copy of your proof of purchase to assist in the evaluation of your repair
- Record your serial number for future reference
- Remove <u>any</u> accessories (sling, scope, scope mounts, case, etc.) unless these items are needed to assist in the evaluation.
- Properly package your <u>unloaded</u> firearm. Do not ship in your hard case (note: Original boxes are not returned with repair)
- Do not send live/loaded or spent ammunition with your firearm.
- Please package the ammunition in a secure carton or box.
- The package should be stuffed to prevent movement.
- Include service request number.
- Shipment of live ammo must be via U.P.S. only.
- Please advise your local U.P.S. mailing center of the contents so that a special Other Regulated Materials-Domestic (ORM-D) label can be applied.

Please let us know of any address change requests by email or phone. Our returns process will take approximately 2-3 weeks to complete and a confirmation email will be sent once we have shipped your firearm.

Should you have any further questions or concerns please don't hesitate to contact us via email (<u>info@remington.com</u> << <u>mailto:info@remington.com</u>>>) or by phone at 800-243-9700, M-F 9am - 5pm, EST. We look forward to helping you resolve this issue!

Mailing Label:
cut here)

Arms Services SR# SR00008313 14 Hoefler Ave Ilion, NY 13357 US

Email:

Attn: Prod Serv # 7195



ARS LABEL REQUEST FORM

DATE: 01/	/04/2012		Service Request #	SR00008313	
QUANTITY: 1			WEIGHT PER PACKAGE:	10 LBS	i
REQUESTED BY: mi	tchelles		email address:	Christy.Mitchell@ren	nington.com
					į
					· .
Business:		Remington Servi	ce		
		PO Box 700 Madison, NC 27	025-0700		i
		www.Remingtor	i.com		
					
		LABEL IN	FORMATION		
MAIL LABEL T	O:	BLACKLAND G	UN WORKS		
		6900 CTY RD 10 TAYLOR, TX	01 16574 US		!
·		SR00008313			:
		Email: blackland	guns@eccwireless.com		
RETURN ITEM	1 TO:	ILN			
		Arms Services			
					. į



4XX596 JAN 4, 2012 ACT WT 10.0 LBS #PK 1 SVC GNDCOM BL WT 10.0 LBS TRACKING# 1Z4XX5969067709489 ALL CURRENCY USI REF 1:SR00008313 REF 2: ALL CURRENCY USD

HANDLING CHARGE 0.00
SHIPMENT PUB RATE CHARGES:
COD 0.00 FRT: 3RD SVC T/P USD DV 0.00 DC 0.00 AH 0.00 TOT PUB CHG 12.03 RS 1.00 DGD

PR

0.00

0.00 ROD PUB+HANDLING ROD 0.00 12.03

ATTN: Prod Serv # 7195





