Remington Arms Co., Inc. Product Service Legal Case #:7221

Case	Int	form	1 at	inn
Case	YFI	IOI II	i ett.	ION

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Obsolete 12/30/2011 1/7/2012 1/9/2012 252054

Customer Information

Last Name City Contact Business First Name Street Zip H 253-229-3245 23413 44th Ave East 98387 Incident Edmond R Duncan Spanaway E erduncan@comcast.net

Incident Information

Claims Repair Est. Medical Treatment Medical Status Codes

PΙ

PD Cause:4038 Could Not Duplicate Concern S Fired when releasing safety

Unknown Concern: 1007 Fired on Safe Release

1/26/12 Per letter with rifle, Duncan acquired this rifle about 20 yrs ago in a gun trade. His son took it out hunting and when he returned to his vehicle to off load the gun, he took the safety off and the gun discharged.cm

Firearm Information

Model/Ga. SKU DOM Mfg. Type Serial Bbl. 700/3006 SPRG 6728175 OY 7/1/1974 Remington CF/BA n/a **Date Purchased** Where Purchased Accessories

GOPHER SHOOTRS FARIBAULT MN

Original Owner

N

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Cash Cash Reim. Settlement Release of Claims Release Date Reimbursement Date Settlement Date APV APV

Per Ilion, offer to replace TPA, clean, test fire at BLSM program price

> Repair/Replacement Repair/Replacement Cost Date

102.31 1/26/2012

1/26/12 Per Ilion, could not duplicate concern. Can offer to replace TPA, clean and test fire at BLSM program price.cm

Examination[Remington/CF/BA]

Sub-Part	Code	Comment
Examiner		B.TRAVIS
Exam Date		1/9/2012
Product Type		RF
Action Type		A
Assigned To		T.NAGLE
4038	Could Not Duplicate Concern	
Description		22" 3006 SPRG
Date Code		OY
Bore Plugged	False	
Bulged	False	
Fired	False	
	Exam Date Product Type Action Type Assigned To 4038 Description Date Code Bore Plugged Bulged	Exam Date Product Type Action Type Assigned To 4038 Could Not Duplicate Concern Description Date Code Bore Plugged False Bulged False

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7221&Type=Case

1/26/2012

	Fired while Obstructed			
	Muzzle/Crown Condition	Slightly Worn; Functioning		
	Firing Pin	Slightly Worn; Functioning		
11	Shroud	Slightly Worn; Functioning		
	Face	Slightly Worn; Functioning		
	Handle	Slightly Worn; Functioning		
	Stop	Slightly Worn; Functioning		
	Condition	Slightly Worn; Functioning		
Extractor	Cut Condition	Slightly Worn; Functioning		
	Ext/Eject Test	False		
	Block Condition	Select		
Locking	Lug Condition	Slightly Worn; Functioning		
	Notch Condition	Select		
3 13	Exterior Condition	Slightly Worn; Functioning		
	Stock Condition	Slightly Worn; Functioning		
	Fore End Condition	Select		
Receiver	Condition	Slightly Worn; Functioning		
	Bulged	False		
	Description		M/700 1	BOLT LOCK SAFETY
Safety	Function	Like new; Functioning		
	Sub-Assembly	Non-ISS		
Sear	Lift	Select	.005	
	Notch	Slightly Worn; Functioning		
	Tests	Test Fired	False	
Feeding Test	116313	False		
Trigger	Condition	Slightly Worn; Functioning	RETA)	NG CLIP ON SAFE OUT OF POSITION
	Pull	Select	5#	
	Altered	False		
	Sub-Assembly	M/700 Bolt Lock		

Service Request

Remington Service PO Box 700



Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700.F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number	Serial Number / Description			Date of R	equest:	12/15/2011
SR00006792	6728175			Date I	Printed:	12/15/2011
	Model 7000	_				
Costomer: ED DUNCAN		Des	tination: Arms Services			
23413 44TH AVE E			14 Hoefler Ave			
SPANAWAY, WA 983	387 US		Ilion, NY 13357 U	JS		
Email: ERDUNCAN@C			Email:			
	te item(s) will be evaluated by our repairs you will be contacted with an estimate b		ed moder our warranty	policy. If it	is your fire	earm will be
Tepatras and terminas. 11 nos,	And will be contracted artif at estimate p	etore work is bestormer.				
	·					•
				•		
					_	
Reason For Return					• • • • • • • • • • • • • • • • • • • •	Late Street
	IS OUT OF FACTORY SPECS			+17		-4.0×10^{10}
Mile, - Indooractorie	o dor or moreser brees				•	
		· · · · · · · · · · · · · · · · · · ·				
Service Request Section		Na Light C			4.4	4-1-2
Parts And Service Details			•		·	
Material Type	Description	Qty Needed	Warranty		Price	Disc Amount
		Needed	·			
•		•				
			•			
THIS IS NOT AN INVOICE.	This is a pre-estimate to repair, reconditi	on, or replace the				
•				Sub	Total:	.00
				Est S	ales Tax:	.00
				Gran	d Total:	\$.00

http://sz0159.ev.mail.comcast.net/service/home/~/SR00006792_SRcopy.jpg?auth=co&lo... 12/18/2011

7221

Proof of Ownership

2211

December 19, 2011

I Edmond R. Duncan acquired the Model 700 Remington Serial Number 6728175 approximately 20 years ago in a gun trade.

This statement is my legal proof of ownership.

The reason for returning the gun to the Remington Arms is my son took the gun out hunting. When he returned to his vehicle to off load the gun, he took the safety off and the gun discharged. This is a safety issue. Please correct.

My phone number is 253-229-3245

Email is erduncan@comcast.net

Edmond R. Duncah

Service Request Number

SR 0000 6792

6728175

Model: 700



RE00252054

could not diphonte concerns CAN offen to Riphace TPA, clean + Mast fine under &CP fon 820. + Shop

Quote

] I SEET T] | JAN 1 6 2012

BY:____





