Remington Arms Co., Inc. Product Service Legal Case #:7655

Case Information

RE# Date Opened 5/9/2012 266937

Date Opened(PS) 5/10/2012

Date Closed 5/10/2012

Incident Date

Pre Lit Obsolete Lit

Customer Information

Business Type Incident

First Name Last Name Mickey Mitchell

Street 10683 Reddick Rd

City Ore City Zip

Contact

Incident Information

Claims

Codes

Repair Est. Medical Treatment Medical Status

75683

State

PΙ

PD

Cause: 4038 Could Not Duplicate Concern Concern: 1005 Unexplained Discharge Safe ON

Unknown

S discharged while on safe

5/18/12 Per note on SR, customer stated that rifle will discharge while on safe.cm

Firearm Information

Mfg. Remington

Type CF/BA Model/Ga.

SKU

Serial Bbl. DOM

Date Purchased

Where Purchased

700/243 WIN Accessories

Reimbursement

n/a Original Owner 6435103 CU 4/1/1971

CROWN WHLSE CO ALBUQUERQUE N M

U

CONCERN: FOS

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Cash Settlement

Reim. Date Cash Date

APV

APV

Settlement Per Ilion, replace TPA, clean, test at BLSM price

Repair/Replacement

Repair/Replacement

Release Date

Cost

Release of Claims

Date

5/18/12 Per Ilion, could not duplicate concern. Trigger assm dirty and rusty. Replace TPA, clean, test at BLSM price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date	•	5/10/2012
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 243 WIN
	Date Code		CU
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7655&Type=Case

5/18/2012

	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
Bolt	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition		
	Ext/Eject Test		
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
Overall	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.010
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	16313	False	
	Condition	Slightly Worn; Functioning	DIRTY,RUSTY
Trigger	Puli	Select	5#
1115861	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	

Verify Repair ADDRESS INFORMATION	7.6	Status: New 4/23/2012 9.40:00 AM
Customer	© Received from	Return To C Received from
Name: MICKEY MITCHELL	and the second of the second o	MICKEY MITCHELL
Address 1: 19683 REDDICK RD	processor and the second	10683 REDDICK RD
Address 2. PO City: OPECITY	Box [PO Box
	Country: JUS	TX Zip Code: 75683 County: US
Contact / Concition Problems Estimate History / Problems Reported Code Desic N123 PORWARD TO PRODUCT SE. M240 BOLT LOCK SAFETY MODIFI. Problems Found Code Desic	Reput Notes	Repairments CON AND LUMP CORRECT T.A. direct prices by Just have TPA, LUMP TIST LUNGER DUR CON BYO + Quale CSR Comments Customer stated that tille will discharge while on safe. MAY 1 5 2012 Reffert Close





