ø

¢

				Pro	on Arms Co., duct Service Il Case #:8077	Inc.				
Case Info	mation									
RE# 286297	Date Oper 10/19/201		Date Opened 10/24/2012		Date Closed 10/24/2012	Incid	ent Date	Pre Lit	Lit	Obsolete
Customer	Information									
Туре	Business	First Name	Last Name	Street	City	State Zip	Age	Ċ	ontact	
Reporter	Poughkeepsie Police Dept	Lt. Remsen	Poughkeepsie Po	62 Civic Center Plaza	Poughkeepsie				-451-40 E fpoughk	00 eepsie.com-
Incident I	formation									
	Claims		C	Codes		Repair E	st. Medic	al Treatme	nt Med	ical Status
PI						•				
PD		Cauca	:4038 Could	Not Du-	licate Concerr	•				
S Fired action	when closing		ern:1008 Fired			1	Ľ	Jnknown		
С			·							
fired on 2	er note with rif separate occas s the bolt was b	ions while	a new round v	was being	chambered. Ir	hoth instan	ces a round	t was fired,	the action	on was
Firearm Ir	formation									
Mfg	•		ype		odel/Ga.	SKU	Serial		DC	
Remin	-		/BA		'308 WIN	25711		28 XA [,] 1/8/.	2007 10	:38:22 AM
Date Pure			Purchased		cessories Ori	ginal Owne U	r			
CONCER	N: SLAM FIR		E POLICE DE	281.		U				
Ammuniti	on Informatior	- None D	efined		- •					
	ducts Informati	ion - None	Defined							
Settlemen	t									
				Remin	gton/700/CF/B	A			 .	a 1
S	ettlement	Rele	ease of Claims	R	lelease Date	Reimbu	rsement s	Cash Settlement	Reim Date APV	Date
TPA, cle	, offer to replac an and test fire normal cost									
		Repai	ir/Replaceme Cost	nt Repa	ir/Replaceme Date	nt				
11/5/12 Pe normal co	er Ilion, could i st.cm	not duplica	ate concern. Ru	ist and de	bris in action.	Can offer to	replace Tl	PA, clean an	d test fi	re at 1/2

Examinati	on[Remington	/CF/BA]								
Part	Su	b-Part		Code	: <u> </u>	_,,	C	omment]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		10/24/2012
ļ			[

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=8077&Type=Case

11/5/2012

PrintDisplay

,


₹

	Product Type		RF
Examination	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
	Description		26" 308 WIN HB
	Date Code		XA
Barrel	Bore Plugged	False	
	Bulged	False	
••• •	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly-Worn; Functioning -	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning]
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning]
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	RUST AND DEBRIS IN ACTION UNDER STOCK
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Dessive	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	·
	Description		STANDARD SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS]
	Lift	Select	012
Sear	Notch	Slightly Worn; Functioning	
	Tasta	Test Fired	False
Feeding Test	Tests	False]
	Condition	Slightly Worn; Functioning]
Triggor	Pull	Select	5#
Trigger	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=8077&Type=Case

11/5/2012

.



Notes:

Rifle was used during FBI sniper training course in October 2012. It was reported that rifle slam fired on two (2) separate occasions (on separate dates) while a new round was being chambered.

In both instances a round was fired, the action was worked, as the bolt was being pushed forward and the handle was beginning to be locked down the weapon fired.

. .





