PrintDisplay Page 1 of 2

> Remington Arms Co., Inc. Product Service Legal Case #:8765

0.00	Inforr	n oti on

RE# Date Opened Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 306089 3/26/2013 4/3/2013 4/3/2013

Customer Information

Zip Business First Name Last Name Street City Contact Type State Age H 317-258-4690 Incident David 1525 Nashua Ct. Indianapolis 46260 E jdjack@gmail.com

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PI

PD Cause: 4038 Could Not Duplicate Concern Discharges without pulling S Concern:1008 Fired on Bolt Closing trigger

Unknown

C

Service Request# 47677. No correspondence with rifle. CSR Notes in repair system: "Customer states the rifle discharges without touching the trigger." df 4/8/13: I called customer. He stated he bought gun new from a dealer and took it out to private property to target shoot around the 1st part of March. He said on the 3rd round the rifle fired when he closed the bolt. He said he had not touched the trigger at all. He stated the weather outside was 53-55 degrees & overcast, no rain, no snow. Customer then stated that he had researched the Model 700 before he bought it & saw all of the consumer information and the CNBC episode but he thought it was made up until the incident happened to him. He stated when he gets the gun back he is going to sell it - he will never trust it again. df

Firearm Information

Mfg. Remington

Type CF/BA

Model/Ga. 700/308 WIN

SKU 85479

Serial Bbl. G7125158 XF

DOM

**Date Purchased** 

Accessories

**Original Owner** 

12/16/2011 6:37:10 AM

Where Purchased AMERICAN ROD & GUN

U

CONCERN:DISCHARGES WITHOUT PULLING TRIG

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date

Reimbursement

Cash Settlement Reim. Date Cash Date APV APV

Per Ilion: Replace TA @ n/c -

goodwill gesture

Repair/Replacement

Repair/Replacement

Cost

\$50

4/4/13: Per Ilion: Could not duplicate concern. To restore confidence in rifle, will replace TA, check over & test @ n/c - goodwill gesture. df

Examination[Remington/CF/BA]

Sub-Part	Code	Comment	
Examiner		B.TRAVIS	
Exam Date		4/3/2013	
Product Type		RF	
Action Type		A	
Assigned To		S.NICHOLS	
4038	Could Not Duplicate Concern		
Description		24" 308 WIN	
Date Code		XF	
Bore Plugged	False		
=======================================	Exam Date Product Type Action Type Assigned To 4038 Description Date Code	Exam Date Product Type Action Type Assigned To  4038 Could Not Duplicate Concern Description Date Code	Exam Date   4/3/2013

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=8765&Type=Case

PrintDisplay Page 2 of 2

Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Like new; Functioning	
Bolt	Firing Pin	Like new; Functioning	
	Shroud	Like new; Functioning	
	Face	Like new; Functioning	
	Handle	Like new; Functioning	
	Stop	Like new; Functioning	
Extractor	Condition	Like new; Functioning	
	Cut Condition	Like new; Functioning	·
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Like new; Functioning	
Overall	Stock Condition	Like new; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Like new; Functioning	
	Bulged	False	
Safety	Description		XMP SAFETY
	Function	Like new; Functioning	
Sear	Lift	Select	.011
	Notch	Like new; Functioning	
	T4-	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Like new; Functioning	
	Pull	Select	4#
	Altered	False	FACTORY SEALANT PRESANT
	Sub-Assembly	X-Mark Pro	







