Page 1 of 3

Remington Arms Co., Inc. **Product Service** Legal Case #:9235

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete

322326 9/26/2013 9/27/2013 9/27/2013

Customer Information

Type Business First Name Last Name Street State Zip Age Contact

Incident 3000 Breard St Monroe LA 71201 H 318-388-3788 Tyner Petrus

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause:4006 Altered Adjustments or Components

Unknown

S FSR Concern: 1007 Fired on Safe Release

C

Per letter from Tyner-Petrus Hardware, "When you take it off safety it will fire sometimes." jbi

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. DOM

3/7/2003 Remington CF/BA 7/260 REM 24781 7785480 AX 10:34:12 PM

Date Where Original Accessories Purchased

Purchased Owner

TWO PIECE BASE, RECOIL SPORTS SOUTH U **PAD BOOT** INC

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/7/CF/BA

Reim. Cash Reimbursement Settlement Settlement Release of Claims Release Date Date APV

Offer to replace trigger assembly, check over, and test at 50% discount

> Repair/Replacement Repair/Replacement Date

Cost

9/30/13: Per Ilion, "trigger assembly set screws altered, trigger is not returning properly. replace trigger assembly, check over and test fire at 1/2 normal cost." jbi

Examination[Remington/CF/BA]

	Part	Sub-Part	Code	Comment	
1					

http://cps03sp01.remington.com:99/Remington PSA/PrintDisplay.aspx?ID=9235&Type=...

PrintDisplay Page 2 of 3

	Examiner		B.TRAVIS
	Exam Date	_	9/27/2013
Examination	Product Type		RF
	Action Type	<u>]</u>	A
	Assigned To		S.NICHOLS
Cause	4006	Altered Adjustments or Components	
	Description]	20" 260 REM
	Date Code]	AX
	Bore Plugged	False	
	Bulged	False	
Barrel	Fired	False]
	Fired while Obstructed		_
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	_
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	<u>_</u>
	Exterior Condition	Slightly Worn; Not Functioning	
Overail	Stock Condition	Slightly Worn; Functioning	CUT AND LENGTHENED
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description		STANDARD SAFETY
Safety	Function	Like new; Functioning	
•	Sub-Assembly	ISS	i

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9235&Type=... 10/1/2013

	Lift	Select	.014
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	1 ests	False	
	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING PROPERLY WILL FOLLOW DOWN
Tei 222	Pull	Select	2.5#
Trigger	Altered	True	SET SCREWS ALTERED RED SEALANT ON SCREWS
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE, RECOIL PAD BOOT

Quotation

Remington Service PO Box 700

Estimating Report

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Number RE00322326		Serial Numb 7785480 Model 7 Co			ЕМ					te Date:	09/26/2 09/30/2 10/01/2	.013	
Customer: TYNER PE 3000 BREAI MONROE,	RD ST	US						rn To: TYNER PETI 3000 BREARI MONROE, LA	O ST	S			
Please Circle On							••		_	-			-
VISA MC	DISCO	ER Card	No	PO Num	her:			Ex	cp.Date				
Open Accoun	и. к		·	1 () 140111	ou								
Approval Signate	ure:								Date:				
Daytime Phor	ne: ()			Time to	o Call:							
If you desir	re any chan	ge, please use	the reverse	side for you			ark this b	ox.					
Reported M100 - SEE C M123 - FORW		PRODUCT SI			ION		FOR	WĀRD TO PR	ODUCT SEI	RVICE FOR	INSPE	CTION	
					Fechnician	Comr	nents						_
trigger assembly	set screws	aitered, trigge	r is not retui	rning proper	ly. replace	trigger	assembly	,check over an	id test fire at	1/2 normal	cost.		
	·····	ESTIMATE	(note: C.O	.D./Shipping	and Han	dling (Charges a	re NOT Inclu	ded in this (Quote.)			-
Material	Type	Descrip		· · · · · · · · · · · · · · · · · · ·	3		Qty Needed	Warranty	Qty From Inv	Price	Disc	Amount	
F305574B 4000114 4000119	Part Service Service		IPPING & H	TRIG ASSB IANDLING			1 1 1	Billable Billable Billable	1 1 1	97.00 17.00 23.00	0	48.50 17.00 11.50	
										ıb Total: et Sales Tax	·	77.00 3.08	
									Gi	rand Total:		\$80.08	

TYNER-PETRUS HARDWARE STORES

IN REPLY REFER TO

Nº 2508 A+3/03



9235

SPEED-LETTER 2014

3000 Breard Street • Monroe, LA 71201 318-388-3788 • Fax 318-388-0911 bill@tpoutdoors.com

(This letter, a copy of which is in our files, is sent to you in writing, so as to get our message into your hands without the delay occasioned by regular office routine.)

Customer Detvice Dept.	
TO Remington Arms Inc.	Date 09/19 /2013
14 HoffER Ave.	Subject
ILION, NY.	1
Place Vil enclare	ed () one Rem, mod 7.
cal. 260 Rem, serial # 778 it off saftey it will fire tell me that this is	5480. When you take
it all salton it will live	sometimer. Mr customer
tell me that this is	the third time that
this grew has been	ent back to Rem
this grin has been s Please check & repair.	
	Thanks.
	Thanks, Jim Mijon
	Mu Pert ma

7785480

Model: 7

PECEIVE A SEP 3 0 2013

B.Y:----

T.A. Set screws Alt. +

This not returning properly

My T.A. chick over + rest

fine At 1/2 Normal east.







