Remington Arms Co., Inc. Product Service Legal Case #:8833

			Floudet Service					
			Legal Case #:8833					
Case Inform								
RE#	Date Opened	Date Opened(PS)	Date Closed	Incid	ent Date	Pre L	it Lit	
308739	4/22/2013	4/23/2013	4/23/2013					Х
Customer In				_		_		
Type	Business		Last Name	Street	City	State	Zip	Age Conta
Reporter Shorty's Shooting Sports		Sports Gunsmith	Shorty's Shooti 219	192 60th St	West Allis	st Allis WI		
ncident Info	ormation							
	Claims		Codes	Repa	ir Est. Med	ical Tre	atment l	Medical Stat
Pl								
PD		Cause:4038 C	Could Not Duplicate Co	ncern		Unknov	m	
S Fires w	hen loading and un	loading Concern: 1008 F	ired on Bolt Closing			Olkilon	V11	
С								
5/1/13 Per n	ote with rifle, "defe	ctive fires when loading and	l unloading also custor	ner would like	a new recoil	plate or	recoil pa	d."cm
Firearm Info	rmation							
Mfg.		Type	Model/Ga.	SKU		Serial	Bbl.	DOM
Remington		CF/BA	721/3006 SPRG			83878	WUU	8/1/1949
Date P	rchased '	Where Purchased	Accessories	Original Owner				
			SCOPE BASE	U				
CONCERN	FBC							
Other Produ Settlement	cts Information - No		Remington/721/CF/B/	A				
S	ettlement	Release of Claims	Release Date	Reimburs		ash		ate Cash Da
	PA, clean and test at program price	t			Sett	lement	APV	APV
DEGI	, program prive	Repair/Replacement	Repair/Replacemen	ıt				
		Cost	Date	•				
		22.30	5/1/2013					
5/1/13 Per II	ion, could not dupli	cate concern. Trigger assm	dirty, sticky and rusty.	Replace TPA	, clean and te	st at BLS	SM progr	am price.cm
Examination	n[Remington/CF/BA	\]						
			7					
	Part	Sub-Part	Code			Com	ment	
		Examiner	<u> </u>	=	3.TRAVIS			
		Exam Date	4	<u>1</u>	1/23/2013			
Examination	n	Product Type		Ī	RF			
		Action Type	╛	<u></u>	A	- tors		
l		Assigned To		[9	SNICHOLS			

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		4/23/2013
Examination	Product Type]	RF
	Action Type]	A
	Assigned To]	S.NICHOLS
Cause	4038	Could Not Duplicate Concern]
	Description		24" 306 SPRG
	Date Code		WUU
	Bore Plugged	False	
Barrel	Bulged	False]
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning]
	Firing Pin	Slightly Worn, Functioning	1

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=8833&Type=Case

5/1/2013

	Shroud	Slightly Worn; Functioning	i
	Face	Slightly Worn; Functioning	┪
Bolt	Handle	Slightly Worn; Functioning	=
			=
	Stop	Slightly Worn; Functioning	_
	Condition	Slightly Worn; Functioning	_
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select]
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Rulged	False]
Safety	Description]	BOLT LOCK SAFETY
Salety	Function	Like new; Functioning	
	Lift	Select	.015
Sear	Notch	Slightly Worn; Functioning	
	T4-	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	DIRTY,STICKY,RUSTY
T :	Pull	Select	3#
Trigger	Altered	True	SEALANT MISSING ON PULL SCREW
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		SCOPE BASE

Service Request

Remington Service PO Box 700

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT 1015

Service Request Number | Serial Number | Description

WITH YOUR RETURN.

SR00050195

Model 721 Center Fire

Customer:

SHORTY'S SHOOTING SPORTS ATTN: GUNSMITH

2192 S 60TH STREET

WEST ALLIS, WI 53219 US

04/09/2013 Date of Request:

Date

Printed: 04/09/2013

Destination:

Arms Services

14 Hoefler Ave

Ilion, NY 13357 US

Email:

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm-will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

M240 - BOLT LOCK SAFETY MODIFICATION

Service Request Section

Consumer stated that the gun went off when the consumer was chambering a round,

Parts And Service Details

Material

Type

Description

Qty Needed

Warranty

· Price Disc Amount

3878

Model:



APR 2 5 2013

BY:----

could not dup, woncern J.A. dinty, sticky presty. Pup. TAA, clean + TOST UND. BCP Con & 20 +

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total:

.00

Est Sales Tax:

.00

Grand Total:

\$.00

Remington Repair

Remington Model 721 30/06 SNH 83878

Defective Fires when localing and unlocaling also constoner would like a new recoil plate or recoil Pease cell with price on recoil plate or peal with installation.

Please call Mike @ (414) 931-9155

Thank You ... Mike Kaminskii









