Remington Arms Co., Inc. Product Service Legal Case #:9514

Case Information

RE# **Date Opened** Date Opened(PS) Pre Lit Lit Obsolete **Date Closed** Incident Date 328256 11/20/2013 11/21/2013 11/21/2013

Customer Information

Last Type Business Street City State Zip Age Contact Name Name

Rt. 2 Box Birch Incident Justice Baker MO 65438 2696 Tree

Ε tiffany@robertshardwoodflooring.com

H 417-934-0028

Incident Information

Claims Codes Repair Est. **Medical Treatment Medical Status**

PΙ

PD Cause:4015 Improper Maintenance

Unknown

Concern:1007 Fired on Safe Release S FSR

C

Service Request # 67277 - "Says the rifle will fire going from safe to fire". df

Firearm Information

Mfg. Remington

Type CF/BA

Model/Ga. 700/270 WIN SKU n/a

Serial Bbl. DOM B6413876 DC 9/24/1982

Date Purchased Where Purchased Accessories Original Owner

P B ENTERPRISE MT HOLY N C

U

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Reim. Cash Cash Release of Claims Settlement Release Date Reimbursement Date Date Settlement APV APV

Per Ilion - Quote to repair @ a discount

> Repair/Replacement Repair/Replacement Cost Date

11/22/13: Per Ilion - Not part of BLM. TA dirty, sticky & rusty causing parts to bind & work sluggish. Replace TA, check over & test at 1/2 cost - quote. df 11/26/13: Customer spoke with a CSR, apprvd & paid quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9514&Type=... 12/4/2013

Description Date Code Bore Plugged Bulged Pired Pired while Destructed Muzzle/Crown Condition Piring Pin	Improper Maintenance False False Slightly Worn; Functioning Slightly Worn; Functioning	RF A S.NICHOLS 22" 270 WIN DC
Assigned To 1015 Description Date Code Bore Plugged Bulged Fired Fired while Destructed Muzzle/Crown Condition Firing Pin	False False Slightly Worn; Functioning Slightly Worn;	S.NICHOLS 22" 270 WIN
Assigned To 1015 Description Date Code Bore Plugged Bulged Fired Fired while Destructed Muzzle/Crown Condition Firing Pin	False False Slightly Worn; Functioning Slightly Worn;	22" 270 WIN
Description Date Code Bore Plugged Bulged Pired Pired while Destructed Muzzle/Crown Condition Piring Pin	False False Slightly Worn; Functioning Slightly Worn;	
Date Code Bore Plugged Bulged Fired Fired while Distructed Muzzle/Crown Condition Firing Pin	False False Slightly Worn; Functioning Slightly Worn;	
Bore Plugged Bulged Fired Fired while Obstructed Muzzle/Crown Condition Firing Pin	False False Slightly Worn; Functioning Slightly Worn;	DC]
Bulged Fired Fired while Obstructed Muzzle/Crown Condition Firing Pin	False False Slightly Worn; Functioning Slightly Worn;	
Fired Fired while Distructed Muzzle/Crown Condition Firing Pin	False Slightly Worn; Functioning Slightly Worn;	
Pired while Obstructed Muzzle/Crown Condition Piring Pin	Slightly Worn; Functioning Slightly Worn;	
Obstructed Muzzle/Crown Condition Firing Pin	Functioning Slightly Worn;	
Condition Piring Pin	Functioning Slightly Worn;	
Tring Pin	Slightly Worn; Functioning	
	Slightly Worn; Functioning	
	Slightly Worn; Functioning	
	Slightly Worn; Functioning	
Stop	Slightly Worn; Functioning	SLUGGISH
	Slightly Worn; Functioning	
	Slightly Worn; Functioning	
Ext/Eject Test	False	
Block Condition	Select	
	Slightly Worn; Functioning	
Notch Condition	Select	
	Slightly Worn; Functioning	
Fore End Condition	Select	
	Slightly Worn; Functioning	
Bulged	False]
Description		STANDARD SAFETY
	Like new; Functioning	
Lift	Select	.012
	ondition ut Condition ut Condition ut/Eject Test lock Condition ug Condition otch Condition otck Condition ore End Condition ondition ulged escription unction	Functioning Slightly Worn; Functioning Slightly Worn; Functioning Slightly Worn; Functioning Ext/Eject Test False False False False Fock Condition Slightly Worn; Functioning Otch Condition Slightly Worn; Functioning Like new; Functioning

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9514&Type=... 12/4/2013

Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,STICKY,RUSTY PARTS BIND, WORK SLUGGISH WILL FOLLOW DOWN
	Pull	Select	8#
	Altered	False	SEALANT PRESANT
	Sub-Assembly	M/700 Non-Bolt Lock	

Quotation

Remington Service PO Box 700

Madison, NC 27025-0700

Estimating Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Number RE00328256		Serial Number / Description B6413876 Model 5770			Date Re Estimate Date Pri	Date:	11/20/2013 11/21/2013 12/04/2013		
Customer: JUSTICE BAKER ROUTE 2 BOX 2696 BIRCH TREE, MO 65438 US			Return To: JUSTICE BAKER ROUTE 2 BOX 2696 BIRCH TREE, MO 65438 US						
Please Circle One VISA MC Open Accoun	DISCO	VER Card NoPO Number:		Ехр	.Date				
) Time			Date:				
Reported M123 - FORW	ARD TO I	PRODUCT SERVICE FOR INSPECTION FETY MODIFICATION	oblems Found	RWARD TO PRO	DUCT SER	VICE FOR	INSPE	CTION	
not part of bolt lo test fire at 1/2 nor		Technicia m.trigger assembly dirty,sticky and rusty causin	an Comments - ng parts to bind	and work sluggish.	replace trigg	ger assembl	y,check	over and	
Material	Туре	ESTIMATE (note: C.O.D./Shipping and Ha Description	indling Charge Qty Needed	Warranty	ed in this Q Qty From Inv	uote.) Price	Disc	Amount	
F305570B 4000114 4000119	Part Service Service	X-MARK PRO 700 TRIG ASSB RH BL. GR-SHIPPING & HANDLING (GUN RI GR-TEST	ACK (OS) 1	Billable Billable Billable	1 1 1	97.00 17.00 23.00	0	48.50 17.00 11.50	
			11/26/ Paid	13					
			1410						
						Total: Sales Tax:		77.00 2.05	
					Gra	nd Total:		\$79.05	

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700.F:336-548-7801

www.remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service.PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

7211 D69/8 , Õ12

Service Request Number

Serial Number / Description

SR00067277

B6413876 Model 5770

Customer: JUSTICE BAKER

ROUTE 2 BOX 2696 BIRCH TREE, MO 65438 US

Date of Request:

11/12/2013 Date Printed: 11/12/2013

Destination: Arms Services

14 Hoefler Ave

Ilion, NY 13357 US

Email: tiffany@robertshardwoodflooring.com

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M240 - BOLT LOCK SAFETY MODIFICATION

Service Request Section

HE ALSO SAYS THE RIFLE WILL FIRE GOING FROM SAFE TO FIRE

Parts And Service Details

nisperial

Type

Description

Qtv Needed

Warranty

Disc Amount

Not PARK of DLP T. A. dirty Sticky + Musty
T. A. dirty Sticky + Musty
CHUSING PARTS to Rind +
CHUSING PARTS TO RING
OUR OF TUST AT 1/2 COST.

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the

Sub Total: Est Sales Tax: .00 .00

Grand Total:

\$.00







