Remington Arms Co., Inc. Product Service Legal Case #:9616

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** 329295 12/5/2013 12/6/2013 12/30/2013

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Dearmond 1133 Burke Dr Gallup NM 87301 Incident

H 505-879-0773 E jdearmond2002@yahoo.com

Pre Lit Lit Obsolete

Incident Information

Medical Medical Repair Claims Codes Status Est. Treatment

PΙ

PD shot bloe in

Could Not Duplicate Cause:4038

Concern roof.

Unknown

S FSR Concern: 1007 Fired on Safe Release

 \mathbf{C}

Per SR00068375 Service Request Section, pushed safety off and firearm went off. jbi

Firearm Information

Mfg. Remington

Type CF/BA Model/Ga.

SKU N/A

Serial Bbl.

DOM 6699952 XX 12/1/1973

Date Purchased

Where Purchased

700/243 WIN Accessories

Original Owner

TWO PIECE BASE

U

CONCERN: FSR.PUT HOLE IN ROOF

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement

Release of Claims

Cash

Cash Reim.

Release Date

Reimbursement

Settlement

Date Date APV APV

quote to repair BLM

> Repair/Replacement Repair/Replacement Cost Date

> > \$27

12/9/13: Per Ilion, could not duplicate concern. jbi 12/20/13: I emailed Ilion, to quote under BLM. jbi 12/30/13: I called Jeff Dearmond, he approved quote with a credit card. jbi

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9616&Type... 12/30/2013

Page 2 of 3

	Exam Date		12/6/2013
	Product Type	Ī	RF
Examination	Action Type	ĺ	A
	Assigned To	Ę	S.NICHOLS
Cause	4038	Could Not Duplicate Concern	
	Description		22" 243 WIN
	Date Code	<u> </u>	XX
	Bore Plugged	False	
D1	Bulged	False	
Barrel	Fired	False	
	Fired while Obstructed	1	
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	ACTION UNDER STK VERY DIRTY
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Lift	Select	.008
Sear	Notch	Slightly Worn; Functioning	

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9616&Type... 12/30/2013

		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,RUSTY
	Pull	Select	5#
	Altered	False	SEALANT PRESANT
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

Quotation

Remington Service PO Box 700

Madison, NC 27025-0700

Estimating Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REBLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Number RE00329295	66	rial Number / Description 199952 odel 700 Center Fire Caliber:	243 WIN			Date Rec Estimate Date Pri	Date:	12/02/20 12/26/20 12/30/20	013
Customer: JEFF DEARM 1133 BURKE GALLUP, NM	DRIVE				rn To: JEFF DEARMO 1133 BURKE D GALLUP, NM	DRIVE			
Please Circle One: VISA MC Open Account	DISCOVE	R Card No PO 1	Number:		Exp	o.Date			
Daytime Phone	Approval Signature: Date:								
Reported M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION M240 - BOLT LOCK SAFETY MODIFICATION M1240 - BOLT LOCK SAFETY MODIFICATION M240 - BOLT LOCK SAFETY MODIFICATION									
replace trigger assembly, check over and test fire under bolt loock program for \$20.00 + shipping									
Material	Type	STIMATE (note: C.O.D./Ship Description	ping and Han	dling Charges a Qty Needed	re NOT, Includ Warranty	ed in this Q Qty From Inv	uote:) (; Price		Amount
F305570B 4000114 4000116 4000119	Part Service Service Service	X-MARK PRO 700 TRIG A GR-SHIPPING & HANDLI GR-LABOR GR-TEST			Warranty Billable Billable Warranty	1 1 20 1	.00 17.00 1.00 .00	0 0	.00 17.00 20.00 .00
						Est	Total: Sales Tax: nd Total:	:	37.00 1.85 \$38.85

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the

Est Sales Tax:

Grand Total:

\$.00

Service Request

Remington Service
PO Box 700

Madisen, NC 27025-0700

Parts and Repairs: P:800-243-9700 F:336-548-7801 www.Remington.com
This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number	Serial Number / Description		Date	of Request:	11 20:2013
SR00068375	6699952		Date	Printed:	11 20 2013
Customer: JEFF DEARMOND 1133 BURKE DRIVE GALLUP, NM 87301	Model US	De	tination: Arms Services 14 Hoefler Ave Ilica, NY 13357 US		
	yzhoo.com ne item(s) will be evaluated by our repa you will be contacted with an estimate		Email: ed under our warranty policy.	If it is your fir	earm will be
					,
Reason For Return M240 - BOLT LOCK SA	FETY MODIFICATION				
gun Live	LAND PUT OF	ohen safe a hole of	tywast 2007	um	doff
Paris And Service Details Material Tyro	Description	Qtv Needed	Wastanty	Price	Disc Amount
00050	,				



BY:









