

Remington Arms Co., Inc.
 Product Service
 Legal Case #:9280

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
324587	10/18/2013	10/4/2013	10/21/2013				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Michael	Endicott	HC68 Box 28	North Springs	WV	24869		H 304-664-9568

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015	Improper Maintenance		
S	FSR	Concern:1007	Fired on Safe Release	Unknown
C				

10/4/13: Customer called in. He stated the gun had a FSR last year. He did not have a date. No damage, No injury per customer. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7MM REM MA	25803	C6460376	RJ	11/2/1989
Date Purchased	Where Purchased	Accessories	Original Owner			
	OUTDOOR SPORTS HQ. INC., #1		N			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined


Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair @ a discount						
	Repair/Replacement Cost	Repair/Replacement Date				

10/8/13: Mailed ARS, letter, SR paperwork. Box order# 1549418. df 10/23/13: Per Ilion - TA dirty & rusty - trigger is binding on side plates. Replace TA, check over & test at 1/2 cost - quote. 10/24/13: Customer called for status. I went over exam with him & he wants rifle repaired & will mail a check for payment with approval. df

Examination[Remington/CF/BA]



Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		10/21/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4015	Improper Maintenance	
Barrel	Description		24" 7MM REM MAG
	Date Code		RJ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
	Lift	---Select---	.012

Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,RUSTY TRIG BINDING WILL FOLLOW DOWN
	Pull	---Select---	8.5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	

Quotation

Remington Service

PO Box 700
Madison, NC 27025-0700

Estimating Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Number RE00324587	Serial Number / Description C6460376 Model 700 Center Fire Caliber: 7 MM REM MAG	Date Received: 10/18/2013 Estimate Date: 10/24/2013 Date Printed: 10/24/2013
Customer: MICHAEL ENDICOTT HC68 BOX 28 NORTH SPRINGS, WV 24869 US	Return To: MICHAEL ENDICOTT HC68 BOX 28 NORTH SPRINGS, WV 24869 US	

Please Circle One:
 VISA MC DISCOVER Card No. _____ Exp.Date _____
 Open Account: R _____ PO Number: _____

Approval Signature: _____ Date: _____
 Daytime Phone: (____) _____ Time to Call: _____

If you desire any change, please use the reverse side for your comments and mark this box.

Reported	Problems Found
M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Technician Comments:
 trigger assembly dirty and rusty, trigger is binding to side plates. replace trigger assembly, check over and test fire at 1/2 normal cost.

ESTIMATE (note: C.O.D./Shipping and Handling Charges are NOT Included in this Quote.)

Material	Type	Description	Qty Needed	Warranty	Qty From Inv	Price	Disc	Amount
F305570B	Part	X-MARK PRO 700 TRIG ASSB RH BLACK (OS)	1	Billable	1	97.00	50	48.50
4000114	Service	GR-SHIPPING & HANDLING (GUN REPAIR)	1	Billable	1	17.00	100	.00
4000119	Service	GR-TEST	1	Billable	1	23.00	50	11.50
							Sub Total:	60.00
							Est Sales Tax:	3.60
							Grand Total:	\$63.60

Remington®

24"
RS 11/3
8.5
1017

October 4, 2013

9280

Michael Endicott
HC68 Box 28
North Springs, WV 24869
Phone: 304-664-9568

Ref # 9280, Model 700, Serial # C6460376

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory. A rifle box will arrive separately.

Please include a copy of this letter and service request to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm.

Sincerely,
Dell Fulcher
Consumer Affairs Administrator
Remington Arms Co, LLC
Phone: 1-800-243-9700 ext 8686
Fax: 336-548-7872

RECEIVED
OCT 23 2013

BY:.....

Serial Number:

C6460376

Model: 700



RE00324587

T.A. dirty + rusty. Trig is
DINDING on side photos.
Req. T.A. check over + test
AT 1/2 cost.

G

Model Number: 700 mm Center Fire		Serial Number: C6460376	
Name: Michael ENICOTI		Date of Purchase: Bought of friend	
Address (no PO Boxes): HC68 Box 28			
City: NORTH SPRING		State: WV	Zip: 24869-9612
Phone (Daytime): 304-664-9568		Fax:	
E-mail Address:			
Please describe your problem: it has been firing shell when safety you take off the safety or when putting shell in and sliding the shell forward			
500 characters left			
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.			
<p>WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.</p> <p>:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.</p>			

Use our UPS label

ARS LABEL REQUEST FORM

DATE: 10/09/2013	Service Request #	SR00063994
QUANTITY: 1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY: fulcherdm	email address:	I WILL MAIL LABEL

Business:	Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com
------------------	---

LABEL INFORMATION

MAIL LABEL TO:	MICHAEL ENDICOTT HC68 BOX 28 NORTH SPRINGS, WV 24869 US SR00063994 Email:
RETURN ITEM TO:	ILN Arms Services



4XX698 OCT 9, 2013 ALL CURR USD 1 OF 1
 SVC GNDCOM ACT WT 10.0 LBS
 TRACKING# 1Z4XX6989086079342
 REF 1:SR00063994
 REF 2:

HANDLING CHARGE 0.00	CHRG:	SVC T/P USD
SINGLE - PIECE PUB RATE	COD 0.00	RS 0.50
DV 0.00	DGD 0.00	SD 0.00
DC 0.00	PR 0.00	SP 0.00
AH 0.00	PUB + HANDLING	10.34
TOT PUB CHG 10.34		

ATTN: Product Service	
------------------------------	--





