PrintDisplay Page 1 of 2

Remington Arms Co., Inc.

				Product Service						
				Legal Case #:8474						
Case Info									t Lit	
RE# Date Opened		Date Opened(P	•	Inc	eident Da	ite	Pre Lit		Obsolete	
296348	1/11	/2013	1/14/2013	1/14/2013						
Customer	Information									
Туре	Business	First Name	Last Name	Street	City	State	Zip	Age		ntact
Incident		D. Brooks	Hodges III	1175 Cross Creek Dr	Franklin	TN	37067	•		830-3328 comcast.net
Incident In	nformation									
	Claims		C	odes	Repa	ir Est.	Medi	cal Treati	ment M	edical Status
Pl										
PD		Caus	e:4006 Altered A	djustments or Components	s					
S Fires	when closing	bolt Cond	ern:1008 Fired on E	Bolt Closing			,	Unknown		
С						•				
loaned it t	o a family m	ember and the	y retumed it dirty. H	r and used it frequently in le cleaned the rifle and not roughly bolt back inserted	ticed the tr	igger see	med a	little more	e sensitive	. He did not
		_	was repeatable.cm	rew the bolt back, inserted	a roung ar	io upon s	eaung	uie doit u	te rine ur	ca .
Firearm Ir	nformation									
Mfg.			Туре	Model/Ga.	Model/Ga. SKU			Serial	Bbl.	DOM
Remington			CF/BA	700/22-250 REM				345072		5/1/1968
Date Purchased		Whe	re Purchased	Accessories TRIG SHOE	Original Owner U		er			
CONCER	:N:FBC									
Ammuniti	ion Informati	on - None De	fined							
Other Pro	ducts Inform	ation - None I	Defined							
Settlemen	it									
				Remington/700/CF/BA						
	Settlement		Release of Claims	Release Date	Reimb	ursemen		Cash	Reim. Da	ate Cash
D 11'			receive of Clarina	resease Date	renno	ui seinen	* Se	ttlement	APV	Date APV
	replace TPA LSM program									
ut Di	com program	•	Repair/Replacemei	nt Repair/Replacemen	12					
		•	Cost	Date						
			29.04	1/17/2013						
			yed inspection info. ogram price.cm	He approved repair.cm 1/	17/13 Per 1	lion, trig	ger ass	sm dirty ai	ıd set scre	ws altered.
Examinati	ion[Remingto	on/CF/BA]								
								· · · · · · · · · · · · · · · · · · ·		
ļ	Part		Sub-Part	Code		D. TD.		Comi	nent	

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		1/14/2013
Examination	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4006	Altered Adjustments or Components	
	Description		24" 22-250 REM HB
	Date Code		KR
	Bore Plugged	False	
ı.	Bulged	False	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=8474&Type=Case

1/17/2013

	Fired	False				
Barrel	Fired while Obstructed					
Daret	Muzzle/Crown Condition	Slightly Worn; Functioning				
	Firing Pin	Slightly Worn; Functioning				
	Shroud	Slightly Worn; Functioning				
Bolt	Face	Slightly Worn; Functioning				
	Handle	Slightly Worn; Functioning				
	Stop	Slightly Worn; Functioning				
	Condition	Slightly Worn; Functioning				
Extractor	Cut Condition	Slightly Worn; Functioning				
	Ext/Eject Test	False				
	Block Condition	Select				
Locking	Lug Condition	Slightly Worn; Functioning				
	Notch Condition	Select				
	Exterior Condition	Slightly Worn; Not Functioning				
Overall	Stock Condition	Slightly Worn; Functioning				
	Fore End Condition	Select				
p .	Condition	Slightly Worn; Functioning				
Receiver	Bulged	False				
0.64	Description		BOLT LOCK SAFETY			
Safety	Function	Like new; Functioning				
	Lift	Select	.007			
Sear	Notch	Slightly Worn; Functioning				
	T. 4	Test Fired	False			
Feeding Test	Tests	False				
	Condition	Slightly Worn; Not Functioning	DIRTY.FOLLOWS DOWN ON NULL TEST			
Trigger	Pull	Select	2#			
	Altered	True	SET SCREWS ALTERED			
	Sub-Assembly	M/700 Bolt Lock				
Non-Remington Components	Description		TRIG SHOE			

Service Request

Remington Service PO Box 700

K 725/2

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700 F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Date of Request: 01 07 2013

Date Printed: 01.07 2013

Service Represe Number Serial Number / Description SR00040755 345072

A 10.7 12 10.21 Customer:

Model

D BROOKS HODGES III 1175 CROSS CREEK DR. FRANKLIN, TN 37067-4035 US

Destination:

Email:

Arms Services 14 Hoeiler Ave Ilion, NY 15357 US

Emzil: dbhiii@comcast.net

-Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your frearm will be

repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M240 - BOLT LOCK SAFETY MODIFICATION

Service Request Section

Parts And Service Details Material

Type

Description

Qtv Needed

Warrancy

Price Disc Amount

T.A. dirty + sets creus Alt.

Typ TPA, chart Tusi unlight

for 1820. +

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the

Sub Total: Est Sales Tax:

.00 .00

Grand Total:

\$.00

January 9, 2013

In regards to: Remington Model 700, .22-250 Heavy Barrel, SN 345072, SR# SR00040755

D. Brooks Hodges III Arms Services SR# SR00040755 14 Hoefler Avenue Ilion, NY 13357

To Whom It May Concern,

SUBJECT: M240 - BOLT LOCK SAFETY MODIFICATION AND SPECIAL REQUEST

This rifle was purchased new by myself around 1966-1968 from Oakwood Sporting Goods in Louisville, KY. At the time of purchase, Oakwood added a Leopold scope and trigger extension (widened). I was able to remove the scope and mount and leather-strap but did-not have the small hex wrench to remove the trigger extension. I would like to get that extension back if you have to replace the trigger assembly as part of the safety modification.

The rifle was used frequently (<1000 rounds) for varmint control and target practice in the late 60's and early 70's and only infrequently (<100 rounds) since then. About 5 years ago, I lent the rifle to a family member (after cleaning and performing various function checks) and received it back in a less clean state than when it was borrowed. I cleaned the rifle thoroughly and noticed the trigger seemed a little more sensitive than I had remembered it previously—but wasn't concerned. Since that time, it has not been fired.

Several months ago, I had the need to mitigate a coyote problem, and took the rifle to a local range as prep. I drew back the bolt assembly and inserted a factory round, and upon seating the bolt, the rifle fired unexpectedly (prematurely). Upon further testing, this symptom was quite repeatable and I must assume the issue lies in the trigger mechanism. Hope this explains the current condition.

I also own the same model in a .222 caliber that was purchased by my now deceased father in the late 60's early 70's and wondered if this rifle might have a similar problem. I have not tested this rifle due to safety concerns. Please let me know if I should be concerned.

Sincerely,

D. Brooks Hodges III

Brigadier General (Ret), USA

1175 CROSS CREEK DRIVE FRANKLIN, TN 37067-4035 E-MAIL: DBHIII@COMCAST.NET CELLPHONE: (615) 830-3328







