+ shipping.

Remington Arms Co., Inc.
Product Service
Legal Case #:9410

					oduct Servi al Case #:9						
Case Info	ormation				,	,					
	RE# Date Opened Date Op		Date Ope 11/5/2					ent Date	Pre Lit I	.it (Obsolete
Custome	r iniormati		T4								
Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Cont	act	
Incident		David	Jernigan	22 Jason Rd	Lumberto	n NC	28358		H 910-25 E id.jernigan@		
Incident	Informatio	n						•		D. 70P	001010111
	Claim	s			Codes			Repair Est.	Medical		Medical Status
Men C	xplained D tion of Saf	ety Postio	Cause No n Conce	rn:1025 Un Me	tered Adjust mponents explained E ention of Sa er states the	Discharg fety Pos	ge - No sition		Unknow own." jbi	n	
Firearm l	Information	· · · · · · · · · · · · · · · · · · ·									
Mi		•	Type		Model	Ga.		SKU	Serial	Bbl	DOM
Remi	_		CF/BA	•	700/7MM R	EM MA	A	N/A	B6201752	2 CA	4/1/1980
Date Pu	rchased	Who	ere Purchas	sed	Accesso	ories	Orig	ginal Owr	ıer		
CONCE			AIRLESS H					U			
Ammuni	tion Inform	nation - N	one Defined								
			None Defin								
Settleme	nt										
				Remir	ngton/700/C	F/BA					
Sett	lement	Relea	se of Claim	s Ro	elease Date	R	teimbu	ırsement	Cash Settlement	Rein Dat AP	e Date
assemt over, as under	ce trigger oly, check nd test fire bolt lock for \$20.00)									

Repair/Replacement
Cost
S29
Repair/Replacement
Date

11/6/13: Per Ilion, "trigger assembly very dirty and rusty, parts work sluggish and set screws altered. Replace trigger assembly, check over and test fire under bolt lock program for \$20.00 + shipping." jbi 11/11/13: I called customer with quote, he said he would be sending a check in the mail. jbi 12/12/13: I called David Jernigan, and advised that

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9410&Type... 12/12/2013

PrintDisplay Page 2 of 3

the credit card did not go thru. He said that he would call on Monday with new credit card information. jbi

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
Examination	Exam Date		11/5/2013
	Product Type	Ī	RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4006	Altered Adjustments or Components	IMPROPER MAINTENENCE
	Description		24" 7MM REM MAG
	Date Code		CA
	Bore Plugged	False	
	Bulged	False	
Barrel	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	SLUGGISH
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Worn; Functioning	METAL DIRTY,RUSTY
Overall	Stock Condition	Worn; Functioning	
	Fore End Condition	Select	
n	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
C-C	Description		BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Lift	Select	.006
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding	Tests	False	

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9410&Type... 12/12/2013

Test			
	Condition	Slightly Worn; Not Functioning	VERY DIRTY,STICKY,RUSTY WILL FOLLOW DOWN
Trigger	Puli	Select	3#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

Quotation

Remington Service

Madison, NC 27025-0700

Estimating Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Number Serial Number / Description RE00326244 B6201752 Model 700 Center Fire Caliber: 7 MM REM				1AG	Date Rec Estimate Date Pri	Date:	[1/04/2 [1/05/2 [1/07/2	.013		
Customer: DAVID JER 22 JASON F LUMBERTO	ROAD	358 US		Return To: DAVID JERNIGAN 22 JASON ROAD LUMBERTON, NC 28358 US						
Please Circle Or VISA MC		ER Card No.			Exp	Date		-		
Open Accou	nt: R		PO Number:							
Approval Signat	ure:					Date:				
			Time t	o Call:						
		e, please use the reverse si	de for your comments	s and mark this b	oox.				·	
	-		Pro	blems						
		RODUCT SERVICE FOR ETY MODIFICATION	INSPECTION		WARD TO PRO I LOCK SAFET			INSPE	CTION	
			Technician	Comments						
trigger assembly gram for \$20.00		nd rusty,parts work sluggis			er assembly,ched	ck over and t	est fire und	der bolt	lock pro	
Material	Туре	ESTIMATE (note: C.O.E Description)./Shipping and Han	dling Charges a Qty Needed	are NOT Includ Warranty	ed in this Q Qty From Inv	uote.) Price	Disc	Amount	
F305570B 4000114 4000116 4000119	Part Service Service Service	X-MARK PRO 700 T GR-SHIPPING & HA GR-LABOR GR-TEST			Warranty Billable Billable Warranty	1 1 20 1	.00 17.00 1.00 .00	0 0 0 0	.00 17.00 20.00 .00	
						Est	Total: Sales Tax	:	37.00 .00 \$37.00	

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service.PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

Service Request Number

Serial Number / Description

SR00065447

B6201752 Model 5776

Customer:

DAVID JERNIGAN

22 JASON ROAD LUMBERTON, NC 28358 US-

Date of Request:

10/24/2013

Date Printed:

10/24/2013

Destination:

Arms Services 14 Hoefler Ave

flion, NY 13357 US

Email: david.jernigan@gregpoole.com

-Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

M240 - BOLT LOCK SAFETY MODIFICATION

Service Request Section

Consumer states the firezrm went off on its own.

Parts And Service Details Material

Type

Description

Warranty

Price Disc Amount



T.A. very dirty, sticky + rusty,
PARTS WORLZ Sluggish +
Set screws Alt. Ry, T.A. chick
over & Tist and BCP for ZU+

Q

Sub Total: Est Sales Tax: .00 .00

Grand Total:

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the

PS 32586







