Remington Arms Co., Inc. Product Service Legal Case #:8601

Legal Case #:8601 Case Information RE# Date Opened Date Opened(PS) Date Closed **Incident Date** Pre Lit Lit Obsolete 300101 2/8/2013 2/11/2013 2/22/2013 Customer Information Type **Business** First Name Last Name Street City State Zip Contact C 404-803-9320 Incident Charles Mackey 4355 Links Blvd Jefferson GA 30549 E racer71j@aol.com Incident Information Claims Codes Repair Est. Medical Treatment Medical Status PI PD Stock broke Cause: 4038 Could Not Duplicate Concern Unknown S Fired when moving safety Concern: 1007 Fired on Safe Release 2/22/13 Per note on SR, owner has had several discharges when removing the safety. Complete SMP. One misfire caused firearm to come out of consumers hand and broke stock.cm Firearm Information Model/Ga. SKU DOM Mfg. Type Serial Вы. CF/BA 700/7MM REM MA A6504169 DO 9/23/1977 Remington n/a Where Purchased **Original Owner Date Purchased** Accessories SOUTHERN GUN MIAMI FL U CONCERN: FSR, MISFIRE CAUSED FIREARM TO DROP AND BROKE STOCK Ammunition Information - None Defined Other Products Information - None Defined Settlement Remington/700/CF/BA Cash Reim. Cash Settlement Release of Claims Release Date Reimbursement Date Settlement Date APV APV Quoted 1/2 normal price for stock and BLSM program price for trigger Repair/Replacement Repair/Replacement 2/22/13 Quoted 1/2 normal price for stock and BLSM program price for trigger.cm Examination[Remington/CF/BA]

Sub-Part	Code	Comment
Examiner		B.TRAVIS
Exam Date		2/11/2013
Product Type		RF
Action Type		Α
Assigned To		S.NICHOLS
4038	Could Not Duplicate Concern	WILL NEED THE INCIDENT STOCK TO COMPLETE INSPECTION AND/OR TO WARRANT REPLACEMENT
Description		24" 7MM REM MAG
Date Code		DO
Bore Plugged	False	
Bulged	False	
Fired	False	
	Examiner Exam Date Product Type Action Type Assigned To 4038 Description Date Code Bore Plugged Bulged	Examiner Exam Date Product Type Action Type Assigned To 4038 Could Not Duplicate Concern Description Date Code Bore Plugged Bulged False

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=8601&Type=Case

2/27/2013

PrintDisplay Page 2 of 2

	Obstructed]	
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	SLUGGISH
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	Falsc	
Overall	Exterior Condition	Worn; Functioning	ACTION ONLY RECEIVED
	Stock Condition	Select	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	Select	.008
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	TRIGGER IS BENT,APPEARS HAPPENED DURING TRANSIT,ASSM DIRTY
	Pull	Select	3.5#
	Altered	True	SET SCREWS ALTERED SEALANT CHANGED
	Sub-Assembly	M/700 Bolt Lock	

Service Request

Remington Service PO Box 768



Date Printed: 12/06/2012

12 06 2012

Date of Request:

Madison, NC 27025-0766

www.Remington.com

Parts and Repairs: P:800-243-9700/F:336-548-7801 This document is a sammary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guidaline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number | Serial Number / Description

SR00037744

A6504169

Model 700

Customer: CHARLES MACKEY

4355 LINKS BLVD JEFFERSON, GA 30549 US Arms Services 14 Hoefler Ave Hon, NY 19357 US

Email: racer?ij@acl.com -Your request for service on the item(s) will be evaluated by our regainmen to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M240 - BOLT LOCK SAFETY MODIFICATION M515 - STOCK BROKEN

Service Request Section

Has had several dicharges when removing the safety complete SMP and one missive coused firearm to co me out of consumers hand and broke stock replace stock

Parts And Service Details

Material Type Description

Warranty

Price Disc Amount

A6504169

Model:

BY:

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the

Sub Total: Est Sales Tax: .00

Grand Total:

5.00





