

		REM PRT3006B 165GR	40		
		REM R30063 150GR	40		
		TOTAL	200	NO PROBLEMS NOTED.	
GUN	SERIAL#	AMMO	RDS.	M.F.	BOLT OVERRIDE STEM LOW FOLLOW DOWN
A-10	XC 1125	REM R30065 180GR	40		
		REM R30067 220GR	40		
		REM L30062 150GR	40		
		REM PRT3006B 165GR	40		
		REM R30063 150GR	40		
		TOTAL	200	NO PROBLEMS NOTED.	
GUN	SERIAL#	AMMO	RDS.	M.F.	BOLT OVERRIDE STEM LOW FOLLOW DOWN
A-11	XC 1126	REM R30065 180GR	40		
		REM R30067 220GR	40		
		REM L30062 150GR	40		
		REM PRT3006B 165GR	40		
		REM R30063 150GR	40		
		TOTAL	200	NO PROBLEMS NOTED.	
GUN	SERIAL#	AMMO	RDS.	M.F.	BOLT OVERRIDE STEM LOW FOLLOW DOWN
A-12	XC 1127	REM R30065 180GR	40		
		REM R30067 220GR	40		
		REM L30062 150GR	40		
		REM PRT3006B 165GR	40		
		REM R30063 150GR	40		
		TOTAL	200	NO PROBLEMS NOTED.	
GUN	SERIAL#	AMMO	RDS.	M.F.	BOLT OVERRIDE STEM LOW FOLLOW DOWN
A-13	XC 1128	REM R30065 180GR	40		3
		REM R30067 220GR	40	2	REPLACED RECEIVER INSERT ASSY.
		REM L30062 150GR	40		SEAR STICKING, CAUSING THE
		REM PRT3006B 165GR	40		FOLLOW DOWNS.
		REM R30063 150GR	40		