PrintDisplay Page 1 of 3

Remington Arms Co., Inc. Product Service Legal Case #:9109

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 317958 8/12/2013 8/13/2013 8/13/2013

Customer Information

**First** Last Type Business Street City State Zip Age Contact Name Name H 408-595-4191 4919 Mary Jane San Incident CA 95124 Greg Tyrrell Е Way Jose jeri\_tyrrell@msn.com

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause:4006 Altered Adjustments or Components

COLO

Unknown

S FSR Concern: 1007 Fired on Safe Release

С

Per SR00058779 Service Request Section, "Gun went off going from safe to fire." jbi

Firearm Information

Model/Ga. SKU Serial Bbl. DOM Mfg. Type 700/7MM REM MA A6356293 DI 9/20/1976 CF/BA N/A Remington Date Original Where Purchased Accessories Owner Purchased WHITNEY SPTG GDS DENVER SCOPE U

BASE, RINGS

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement Cash Settlement APV APV

Replace trigger assembly, clean, and test fire under bolt lock program for \$20.00 + shipping.

Repair/Replacement Repair/Replacement

Cost Date

\$66

8/14/13: Per Ilion, "trigger assembly set screws altered, ejector is binding in the bolt. Replace trigger plate assembly, repair ejector, clean and test fire under bolt lock program for \$20.00 + shipping." Called Greg Tyrrell with quote. He said he will call back with credit card. Customer called and approved with credit card. jbi

http://cps03sp01.remington.com:99/Remington\_PSA/PrintDisplay.aspx?ID=9109&Type=... 8/14/2013

PrintDisplay Page 2 of 3

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		8/13/2013
Examination	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4006	Altered Adjustments or Components	
	Description		24" 7MM REM MAG
	Date Code		Dl
	Bore Plugged	False	]
	Bulged	False	
Barrel	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	EJECTOR IS BINDING, WILL NOT RETRACT FULLY
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	_
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	7

http://cps03sp01.remington.com:99/Remington\_PSA/PrintDisplay.aspx?ID=9109&Type=... 8/14/2013

Safati.	Description		BOLT LOCK SAFETY			
Safety	Function	Like new; Functioning				
	Lift	Select	.008			
Sear		Slightly Worn; Functioning				
	T4-	Test Fired	False			
Feeding Test	Tests	False				
	IK ADAITIAN	Slightly Worn; Not Functioning	TRIG NOT RETURNING PROPERLY WILL FOLLOW DOWN			
Trigger	Pull	Select	3.5#			
	Altered	True	SET SCREWS ALTERED			
	Sub-Assembly	M/700 Bolt Lock				
Non-Remington Components	Description		SCOPE BASE,RINGS			

## Quotation

## Remington Service PO Box 700

Madison, NC 27025-0700

Estimating Report


Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Number RE00317958		ial Number / Description 356293			Date Received: Estimate Date:	08/12/2 08/13/2					
KI200317936		del 700 Center Fire Caliber: 7 MM REM MAG			Date Printed:	08/14/2					
Customer: Return To:  GREG TYRRELL  4919 MARY JANE WAY  SAN JOSE, CA 95124 US  Return To:  GREG TYRRELL  4919 MARY JANE W  4919 MARY JANE W  SAN JOSE, CA 9510					E WAY						
Please Circle One:											
VISA MC	DISCOVER	Card No		Exp.D	ate						
Open Account: RPO Number:											
Approval Signatu	re:				Date:						
Daytime Phone	e: ()	Time to Cal	1:			•					
If you desire any change, please use the reverse side for your comments and mark this box.											
Reported		Problem: Fai									
	ARD TO PRO			ARD TO PROD	UCT SERVICE FO	R INSPE	CTION				
Technician Comments trigger assembly set screws altered, ejector is binding in the bolt. replace trigger plate assembly, repair ejector, clean and test fire under bolt lock											
program for \$20.0		easelector to omatting in the both replace trigger p.	uce ussernor,	,,opan ojeotor,on	omi ana tost ino an	ici boli k	, or				
		TIMATE (note: C.O.D./Shipping and Handling				,,,,,,	<del></del>				
Material	Туре	Description	Qty Needed	Warranty	Qty Price	Disc	Amount				
F305570B	Part	X-MARK PRO 700 TRIG ASSB RH BLACK (		Warranty	1 .00		.00				
4000114 4000116	Service Service	GR-SHIPPING & HANDLING (GUN REPAIR) GR-LABOR	) 1 20	Billable Billable	1 17.00 20 1.00		17.00 20.00				
4000119	Service	GR-TEST	1	Warranty	1 .00		.00				
		-									
					Sub Total:		37.00				
					Est Sales Ta	X:	.00				
					Grand Total	:	\$37.00				





PECEIVE L AUG 1 4 2013

T.A. set screws Alt. EJect. Binding in Bolt. Lip. TRA, CLEAN+TEST and BLP Con 20+

9



