

Customer Service Data Entry

File Number: 9404 **Arms Service number:** 9710906

Last Name: KING **First Name:** ROBERT

Street: 2638 S. BROOKS CIR **City:** MESA

State: AZ **Zip:** 85202 **Home Ph:**

Work Ph: **Product Type:** F A T O

Type Concern: IS **PI PD P S C** **Concern Code:** 1008

Concern: FIRED ON BOLT CLOSING

Cause Code: 4015 **Cause:** IMPROPER MAINTENANCE

Assigned To: SANITA **Classification:** UNJ UNJ UNC UND J

Settlement Detail: REPAIR AT SPEC PRICE **Settlement Amount:** \$25.00

Date Opened Rem: 6/9/97 **Date Opened by P/S:** 6/9/97 **Caliber:** 30/06

Date of Incident: **Date Closed:** 6/11/97 **Bullet Weight:**

Date to Analysis: **Date from Analysis:** **Manufacturer:** REM

Model: 700 **Serial:** B6303583 **Date Code:** 18 **Date Mfgd:** 2/1/81

RAMAC: 700 **Litigation:** ☐ **PreLitigation:** ☐ **Obsolete:** ☐

Custody: **Comments:**

Time of Modification: 9:08:29 AM **Date of Modification:** 6/11/97

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 97-10906

INITIAL
JJM

CUSTOMER ORDER NO.

ATTN JACK KAST

DATE RECEIVED

06/03/97

DATE OPENED

06/09/97

DATE CODE

LB 2-81

SERIAL NUMBER

B6303583

NEW SERIAL NUMBER

MODEL AND GRADE

700 30-06

ADL

ACCESSORIES

HARD CASE

L/SIGHTS

W/STUDS

FROM:

KING, ROBERT
2638 S BROOKS CIR
MESA

AZ 85202

SHIP TO:

KING, ROBERT
2638 S BROOKS CIR
MESAAZ
85202

CUST NO: 167912 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE 25.00

EXCISE

TAX

INSURANCE

UPS 8.00

PARCEL POST

TOTAL 33.00

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

METAL

MAIN FAULT

Upon receipt we could not duplicate the reported concern.
Examination did reveal that the trigger & rear safety were in
good condition with a heavy safety mechanism. Bolt stop when working properly.
Action needs a good cleaning. Rifle #26345
Repairer Compacted trigger mechanism
with 1/5 mm bolt head type
at 1/2 normal repair cost

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 11/96

DATE: 05-28-97

FROM: Robert King
2638 S. Brooks Cir.
Mesa, AZ. 85202
(602) 491-0389

TO: Remington Firearms Inc.
14 Hoefler Ave.
Ithaca, NY. 14850
Attn: Jack Kast

Mr. Kast,

I am sending my Remington Model 700 ADL (serial # B63033583) into the Remington Firearms Corporation to have the rifles bolt action, firing mechanism and safety inspected. I would also like to have the safety changed from being in the "FIRE" position to the "SAFE" position when operating the bolt. (Non Bolt Lock Safety Installed)

On my last hunting trip, after hiking into my hunting location, I slid the bolt open approximately 2 inches to verify that the gun was loaded. Upon closing the bolt the rifle discharge. The rifle was setting upright on my lap with nothing touching the trigger. I then (AFTER CALMING DOWN) removed the remaining two rounds and called it a day. I have not loaded the rifle since that hunting trip.

Please contact me with any questions.
Thank You,

Robert King