

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 99-06946

INITIAL CUSTOMER ORDER NO.

PS

DATE RECEIVED 03/04/99 DATE OPENED 03/12/99 DATE CODE LU 2-71 SERIAL NUMBER 6309920 NEW SERIAL NUMBER MODEL AND GRADE 700 223 BDL/VAR
ACCESSORIES W/STUDS SOFT CASE

FROM:

SHIP TO:

DAVIS MICHAEL
10440 NW 19TH PLACE
PEMBROKE PINES FL 33026

DAVIS MICHAEL
10440 NW 19TH PLACE
PEMBROKE PINES FL 33026

CUST NO: 206877 C.O.D.

ACCOUNT NUMBER 2293001 ACCOUNT NUMBER N/C PROM. DATE ESTIMATED VIA UPS

GUN CONDITION

- NEW
- LIGHTLY WORN
- WORN
- VERY WORN
- UNREPAIRABLE
- MARRED

REPAIR CHARGE 35.00
EXCISE
TAX
INSURANCE
UPS 8.00
PARCEL POST
TOTAL 43.00

| CUSTOMER CONCERN | AMMO | FUNCTION | FINISH | ACCURACY | FIT | INSPECT |
|------------------|------|----------|--------|----------|-----|---------|
| CYCLE | A1 | B1 | | | | |
| TRIGGER GROUP | | B2 | | | E1 | F1 |
| BOLT ASSY. | | B3 | | | E2 | F2 |
| BARREL ASSY. | | B4 | | | E3 | F3 |
| REC. ASSY. | | B5 | | D2 | E4 | F4 |
| WOOD | | | C1 | D3 | E5 | F5 |
| METAL | | | | | | |

While closing the bolt the firing pin would fall

MAIN FAULT

Upon receipt the rifle was in operation the trigger cog & stop screws have been re-set. The trigger would not retract. The bolt stop released was removed up from being covered with a heavy sticky substance.

PARTS

COMMENTS

26345

Replace the complete trigger assembly with non hot load - current style at 1/2 the normal cost.

Go...

| | | | | | |
|----------------|-------|-------|------|--------|---------|
| REPAIRMAN | PROOF | CLEAN | TEST | TARGET | PATTERN |
| | | ✓ | ✓ | | |
| GALLERY TESTER | DATE | DATE | DATE | DATE | DATE |

OFFICE COPY

RD6925 REV. 7/97

Michael Davis
10440 NW 19th Place
Pembroke Pines, FL 33026
954-295-5597

Wednesday, March 03, 1999

Remington Arms
14 Hoefler Ave.
Ilion, NY 13357


Dear Sirs:

Enclosed please find my Remington 700BDL Varmint .223 Rem s/n 6309920. I recently purchased the gun in the box in unfired condition. I have put about 80 rounds through it and now there is a trigger problem.

When closing the bolt the firing pin falls as if the trigger was held. Per the owners manual, I attempted to adjust the weight of pull but with no success. Your Service Department recommended I return the gun to you and have the trigger upgraded to the current style that allows the bolt to be opened with the safety in the "safe" position.

Please advise if there are any charges by calling me at 954-295-5597.

Sincerely,



Michael Davis