

CC: S. E. Alvis, Jr.
 H. A. Brown, Jr.
 W. A. East
 E. H. Grace
 E. J. Hadden
 W. E. Leek
 W. C. Smith
 E. H. Walker

DAILY PROGRESS REPORT

June 14, 1948

Three more M/722 - 257 Rem. Roberts Cal. have been function tested with the following results:

Gun No.	Rounds Fired	Ammunition Mfg.	Type of Malfunction
33647	0-80	Remington	2 Fails to Feed - last round. Bolt override. Medium functioning.
			1 Fail to Feed - stalled chamber. Fast functioning.
			1 Fail to Feed - last round. Bolt override. Slow functioning.
	81-160	Western	8 Fails to Feed - last round. Bolt override. 7 slow feeding; 1 fast feeding.
	161-200	Winchester	3 Fails to Feed - last round. Bolt override. Slow functioning.

Malfunction rate - 7.5%.

33645	0-80	Remington	4 Fails to Feed - last round. Slow functioning. 3 Fails to Feed - do not charge ammunition - measures over max.
	81-160	Western	8 Fails to Feed - Bolt overrides last shell. Slow functioning. 1 Fail to Fire - light blow.
	161-200	Winchester	5 Fail to Feed - Bolt overrides last shell. Slow functioning.

Malfunction rate - 10.5% ^{8.5%}

33654	0-80	Remington	2 Fails to Feed - Bolt overrides last shell. Slow functioning.
	81-160	Western	8 Fails to Feed - Bolt overrides last shell. Slow functioning. 2 Fails to Fire - light blow.
	161-200	Winchester	2 Fails to Feed - Bolt overrides last shell. Slow functioning.

Malfunction Rate - 7.0%.

Three more M/722 (257 Rem. Roberts cal.) rifles will be functionally fired and accuracy tested, at which time a complete report will be issued.

WEL:MP

W. E. Leek
 Engineering Section, Technical Dept.