

11. Problems:

6. M/121 Action Bar Oper. 40-1 Wall thickness too thin.
 - a. It was decided to allow an added 0.002 to present limit and change Past Practice Record accordingly.
7. M/121 Action Bar Oper. 51 Thickness of rear lug too thin to gage RW-3223.
 - a. It was decided to investigate this operation to determine possibilities of changing gage, changing Past Practice Record limits, or removing Gage RW-3223 from operation.
 - A. Prokop to follow.
8. M/121 Guard Oper. 49 Gage RW-1352 is listed in Process Record but is not on job.
 - a. It was decided to obsolete gage RW-1352.
 - A. Prokop to follow.

Remarks:

1. The current Weekly Quality Index was discussed and necessary corrective action was taken.
2. Period 2/1/50 to date: 17 problems discussed of which 11 are closed and 6 outstanding.

E. Hood
For the Committee