

Ilion, New York
July 10, 1962

R. P. KELLY

XP-100 TRIGGER HOUSING

One of the sample production parts received from you was assembled into the test action and checked for assembly and function. The following points were noted:

1. Countersink on tapped holes too deep on some parts. This should be kept to minimum.
2. Part easily assembled to barrel bracket.
3. Threads OK (diameter).
4. Trigger pivot pin hole alignment good. (No cramping of trigger in housing)
5. General appearance good.
6. Operation satisfactory in assembled action.

H. L. Chambers

HLC:T