

Add

COPY "A" to XP-100 FOLDER

Make certain nylon receiver screw washers (forward and rear) are in correct position against receiver during re-assembly. Also that trigger balance remains centrally positioned on its pin in stock. This will enable top of balance to re-enter slot in trigger link easily. Make certain both receiver screws properly re-enter metal screw escutcheons in stock and tighten action securely.

JFF:T
11-8-62