

after tests on 11-15-65

Rifle 139413.

520r can surface that contacts firing pin head
can surface. Shiny spots showing which means
some wear but not excessive. Corrosion in slight
places.



in contact on flat surface. very
light.

520r surface that contacts connector surface. with
oil on surface it looks like a deposit of rust. when
oil is removed it looks clean & shiny.

connector surface with oil on it looks as though it
has a varnish or rust film. when oil is removed
the surface was shiny & shows the surface that
it is in contact with the 520r.




Rifle 139555

520r can surface same as above



520r surface that contacts connector same as above.

connector surface same as above except that when
oil is removed there are still some spots that look like a
varnish or rust.



prints show
marks