

after tests on 11-15-65

Rifle 139413

5 cam surface that contacts firing pin head
cam surface. Shiny spots showing which means
some wear but not excessive. Corner is similar
place.



in contact on flat surface. very
light.

5 cam surface that contacts connector surface. w/ oil
on surface it looks like a deposit of rust. When
oil is removed it looks clean & shiny.

connector surface with oil on it looks as though it
has a varnish or rust film. When oil is removed
the surface was shiny & shows the surface area
it is in contact with the cam.



Rifle 139555

5 cam surface same as above



5 cam surface that contacts connector same as above.

connector surface same as above except that when
oil is removed there are still some spots that look like
varnish or rust.



prints little
marks