

MODEL 700 SAFETY EVALUATION

SERIAL NO. 6338370 - 25-06 E. Sliwa

As received, all functions work correctly. The rifle shows moderate usage. The rifle is a pre-1974.

- 1. Cocking notch on bolt roughed up.**
- 2. Slight wear mark on left edge of Firing Pin Head.**
- 3. Much large unburned powder particles found throughout action. Six particles found on Floor Plate. Sample .042" Dia. - .082" long.**
- 4. Parts have a generally oily appearance - not excessive, but, could affect cold weather operation.**
- 5. Fire control of welded design not riveted.**
- 6. Adjustment screws have not been tampered with - sealant is still intact.**
- 7. No trigger scrubbing on trigger guard.**
- 8. No interference marks in stock at either trigger or safety position.**
- 9/ Sear works free in housing .**
- 10. Trigger Assembly fits tightly in Receiver.**
- 11. Excessive oil on Bolt Stop.**
- 12. Excessive oil on sides of Sear Safety Cam.**
- 13. Sear shows 70% bearing with Connector.**
- 14. Line on Connector shows satisfactory engagement.**
- 15. Satisfactory clearance between Trigger Connector and Sear.**
- 16. Engagement ok. - Sear Connector**
- 17. Edge of Bolt Stop tore off.**
- 18. Powder particles back in action along Bolt Stop.**

F. E. Martin/nl