

7/9/81

Hammer Marks

- Rough & smooth surfaces - refract light - to give appearance of hammer marks.
- May be caused by Harper Buff. ?
- Should we anneal after GFM - ?
 - equalize energy from both.
- Check surface finish before & after block oxide.
- Slower GFM feed rates