


Chet - Phil - Tim - Sgt

7/23/81

Hammer MARKS - CF

Probable Cause - insufficient belt sanding before buff. (polish)

- 1) - Select Bbs after GFM - Measure dia, Boice Page



- 2) Measure max & min depth of hammer marks off GFM. Boice
3) Belt Sand to various levels - measure depth.
- measure - belt sand (polish) - remeasure - buff & color
4) Microscopically examine after belt sand, pickle & examine (Kush)
5)

Chet - Get sample of Bbl before & after belt change.
Phil to make micro and analyze.

Phil - analyze hammer material

Chet - Make sure stress relief is done on hammers - Have chemist not
"mark" for I.D.

START

7/27/81