


VISUAL INSPECTION

A-23

etch on
rein-
forcement pin.



Lack of Stain

