


Rear Tang Not
Flush with the
Stock.



Stock Rein-
forcement Pins
Are Egg Shaped.

