

M/700 Classic 257 Roberts Cal. Pilot Line Test.

Visual Inspection

Location: R. & D. Photo Lab.

Con ducted by: J. Brooks, E. Ritchie, P. Nasypany, B. Joy, M. Hardy,
C. Powers, W. Warren, J. HEnnings.

Report No. 821672

June 29, 1982

J. Hennings

Page 1

Comments per rifle:

Serial No. 6397205:

- o excess wood margin at safety
- o uneven sanding on stock rails
- o Marris on stock - left side
- o bolt handle finish dull
- o scale - roughness on sides of trigger guard
- o checkering border rough - right side - fore-end.
- o holes split on butt pad.
- o discoloration in finish at butt plate fit.
- o floor plate marris wood when opened fully.
- o dimples on bolt handle.

Serial No. 6394453

- o scale - roughness on sides of trigger guard.
- o rough checkering at grip - both sides.
- o bolt handle slot in stock - rough appearance.
- o bolt handle finish dull.
- o wood chips in rear tang cut on stock.
- o poor repair on stock rail - right side.
- o excess braze on bolt handle.
- o sling swivel off center - (front).
- o poor polish on receiver.
- o poor polish on trigger guard bow.
- o uneven barrel inletting of stock.
- o marr on stock - left side.
- o poor staining of stock on edges.

Serial No. 6396760

- o floor plate bowed.
- o scale - roughness on sides of trigger guard.
- o bolt handle finish dull.
- o poor staining all edges of stock.
- o marris on stock
- o checkering not complete at grip - both sides.
- o uneven barrel inletting.
- o re-inforcing screw break out of finish on left side.
- o off-center checkering of fore-end.
- o toe of butt pad rolled-over.
- o excess wood/metal margin rear of trigger bow.
- o chip on inletting of stock for trigger guard - right side.

Serial No. 6395859

- o scale-roughness on sides of trigger guard.
- o bolt handle finish dull.
- o checkering missed at grip - right side.
- o excess braze on bolt handle.
- o barrel inletting off center.
- o poor staining of stock at edges.
- o chip out of stock by safety.
- o dent in bottom of stock by floor plate.
- o floor plate (hinge area) indenting stock when opened.

Serial No. 6395662

- o poor checkering at grip - both sides.
- o scale - roughness on sides of trigger guard.
- o dull finish on bolt handle.
- o poor stain on stock - all edges.
- o magnaflux stamp obscured.
- o floor plate (hinge area) indenting wood when opened.
- o marks on stock - fore-end right and bottom.
- o edges of stock broken over by floor plate.
- o uneven side wall sanding - trigger guard area.
- o screw holes split on butt pad.
- o poor polish of receiver by side rails.
- o fore-end checkering off center.

Serial No. 6397135

- o scale-roughness on sides of trigger guard.
- o poor fit of floor plate.
- o bolt handle finish dull.
- o metal filings in magazine.
- o sharp edges on both sides of trigger guard.
- o side play on safety (loose).
- o poor color on front trigger guard screw.
- o checkering sealer on bottom of grip.
- o poor stain on stock - all edges.

Serial No. 6396144

- o scale - roughness on sides of trigger guard.
- o missed checkering at grip - right side.
- o rough finish on stock at bolt handle slot and ejection port.
- o rear sling swivel indented into stock
- o safety button twisted inward.
- o no rear retraction of safety.
- o bolt release stack.

Serial No. 6395794

- o scale - roughness on sides of trigger guard.
- o excessive sanding at bottom of grip.
- o excessive wood/metal margin at rear of trigger guard.
- o poor color on safety button.
- o excessive wood/metal margin around tang and safety.
- o rear swivel screw not flush with stock.
- o missed checkering at grip on both sides.
- o dull finish on bolt handle.